

AD-A167 632

REPORT AND RECOMMENDATIONS ON UNDERWATER DAMAGE

1/2

ASSESSMENT PIER 11 MAUA. (U) MYRE CORE NCLAN UA

JASON PROGRAM OFFICE SEP 79 CHES/MAUFAC-TPO-7914

UNCLASSIFIED

N62477-79-C-0037

F/G 13/2

NL2

1 2 3 4 5 6 7 8 9 10

1.0

2.8

2.5

3.15

2.2

1.1

3.5

2.0

4.0

1.8

4.5

1.25

1.4

1.6

FPO  
7914



WISWELL, INC.


1280 POST ROAD, SOUTHPORT, CONN. 06490

203. 559 5204

AD-A167 632

REPORT & RECOMMENDATIONS  
ON UNDERWATER DAMAGE ASSESSMENT  
PIER LIMA  
NAVAL STATION, GUANTANAMO BAY, CUBA

DTIC  
ELECTE  
S MAY 02 1986 D  
D



SEPTEMBER 1979

**DISTRIBUTION STATEMENT A**

Approved for public release  
Distribution Unlimited

DEVELOPED FOR  
CHESAPEAKE DIVISION  
NAVAL FACILITIES ENGINEERING COMMAND  
OCEAN ENGINEERING AND CONSTRUCTION PROJECT OFFICE  
WASHINGTON NAVY YARD  
CONTRACT N62477-79-C-0837

\*Original contains color  
plates: All DTIC reproductions  
will be in black and  
white\*

DTIC FILE COPY

UNDERWATER SERVICES  
CONSULTING  
ENGINEERING

SHIP SURVEYS  
CONDITION REPORTS

MAINTENANCE  
REPAIR

86 4 22 043

Unclassified

SECURITY CLASSIFICATION OF THIS PAGE

REPORT DOCUMENTATION PAGE

1a. REPORT SECURITY CLASSIFICATION  
Unclassified

1b. RESTRICTIVE MARKINGS

2a. SECURITY CLASSIFICATION AUTHORITY

3. DISTRIBUTION AVAILABILITY OF REP.  
Approved for public release;  
distribution is unlimited

2b. DECLASSIFICATION/DOWNGRADING SCHEDULE

4. PERFORMING ORGANIZATION REPORT NUMBER

5. MONITORING ORGANIZATION REPORT #  
FPO 7914

6a. NAME OF PERFORM. ORG. 6b. OFFICE SYM  
Wiswell, Inc.

7a. NAME OF MONITORING ORGANIZATION  
Ocean Engineering  
& Construction  
Project Office  
CHESNAVFACENGCOM

6c. ADDRESS (City, State, and Zip Code)  
3280 Post Road  
Southport, CT 06490

7b. ADDRESS (City, State, and Zip )  
BLDG. 212, Washington Navy Yard  
Washington, D.C. 20374-2121

8a. NAME OF FUNDING ORG. 8b. OFFICE SYM

9. PROCUREMENT INSTRUMENT INDENT #  
N62477-79-C-0837

8c. ADDRESS (City, State & Zip)

10. SOURCE OF FUNDING NUMBERS  
PROGRAM PROJECT TASK WORK UNIT  
ELEMENT # # # ACCESS #

11. TITLE (Including Security Classification)  
Report & Recommendations on Underwater Damage Assessment Pier Lima Naval  
Station, Guantanamo Bay, Cuba

12. PERSONAL AUTHOR(S)

13a. TYPE OF REPORT

13b. TIME COVERED  
FROM TO

14. DATE OF REP. (YYMMDD) 15. PAGES  
79-09 96

16. SUPPLEMENTARY NOTATION

17. COSATI CODES  
FIELD GROUP SUB-GROUP

18. SUBJECT TERMS (Continue on reverse if nec.)  
Underwater inspection, Mooring systems,  
Pier Lima Naval Station, Guantanamo Bay,  
Cuba

19. ABSTRACT (Continue on reverse if necessary & identify by block number)  
Structural assessment and repairability of the steel "H"-piles supporting Pier  
Lima, Naval Station, Guantanamo Bay, Cuba are presented. Field data gathering  
techniques included underwater ultrasonics, underwater and above surface  
visual inspection and measurement, still photography, and underwater (Con't)

20. DISTRIBUTION/AVAILABILITY OF ABSTRACT 21. ABSTRACT SECURITY CLASSIFICATION  
SAME AS RPT.

22a. NAME OF RESPONSIBLE INDIVIDUAL  
Jacqueline B. Riley  
DD FORM 1473, 84MAR

22b. TELEPHONE 22c. OFFICE SYMBOL  
202-433-3881  
SECURITY CLASSIFICATION OF THIS PAGE

BLOCK 19 (Con't)

television. Areas of inspection included existing pile jackets, detailed underwater inspections of piles, pile-pile cap connections, and the existing fender system.

Analysis was conducted using field data and government-furnished information.; Scope of work was limited to assessment of piles on singular basis, with pier system comments and conclusions included in general terms. The pier was ground to have only approximately half of its original capacity. Re-jacketing most of the piles with concrete jackets, re-securing pile-pile cap connections, and installation of a new fender system and batter piles is recommended as a cost-effective repair to bring the pier to approximately 90 percent of its original capacity.



**WISWELL, INC.**

3280 POST ROAD, SOUTHPORT, CONN. 06490

203-259-5204

October 2, 1979

Naval Facilities Engineering  
Command  
Chesapeake Division  
Building 57  
Washington Navy Yard  
Washington, D. C. 20374



Attention: Lcdr. T. R. Brandenburg

Re: Contract No. N624477-79-C-0387  
Inspection of Piling, Pier Lima,  
Naval Station, Guantanamo Bay,  
Cuba

Gentlemen:

Relative to our final report, on above referenced project,  
dated September 1979, please note the following erratum  
and/or changes:

1. Page 14, line 23...delete "stainless"
2. Page 18...delete "316 stainless"
3. Page A-17, line 1...change "Fasteners"  
to "Bolts"
4. Page A-18 should have been transposed with  
page A-21 (i.e. bents 51-55 should have  
been in the beginning of the appendix).
5. Page A-25, line 1...change "BJD" to "DBJ"
6. The last two pages, the reference page  
and the bibliography page should have been  
bound between p. 23 and the Appendix 1  
title page.

Sincerely,


George C. Wiswell, Jr., P.E.  
President

GCW:vs  
UNDERWATER SERVICES

Connection Discussed w/ Wiswell 2 Oct 79.

(Wiswell will include in errata sheet.)

1. P. 14, 3rd #, 4th line — delete the word "stainless."
2. P. 18, Fig. 2, notation for bolts, delete the words "316 stainless"
3. P. A-25 change "BJD" at top of sheet to "DBJ".



Memo

From: S.C. Ling

25 Sept. 79

To: FPO-1B, IEA 21, IEA 23

Subj: Pier Lima, GTMO - Wiswell Insp. Rpt'


1. This is Wiswell's final report. It is supposed to contain all our requests following the review of their draft report.

2. To expedite in house review and hold the number of unmarked copies for distribution to NAVSTA GTMO and LANTDIV, it is requested that you not mark the attached copy. Instead write your comments on a separate sheet and return to me by C.O.B. 26 Sept 79, Wed.

*Shun*

(Review copies:

- 1 C. Chen
- 1 J. Stamm
- 1 J. Baker
- 1 S. Ling






Rec'd on 25 Sept. 79

1 Reproducible of the text (original).

1 Copy of text w/ original photographs (bound)  
4 copies of text w/ xerox copies of } (bound)  
photographs






**WISWELL, INC.**

3280 POST ROAD, SOUTHPORT, CONN 06490

203-259-5204

September 20, 1979



Naval Facilities Engineering  
Command  
Ocean Engineering & Construction  
Project Office  
Washington Navy Yard  
Washington, D.C. 20374

RE: Contract Number N62477-79-C-0837

Gentlemen:

Attached please find the results of our inspection, calculations, and analysis performed under the above-referenced contract.

We feel that this material represents a most cost-effective study within the existing scope of work.

Thank you for the opportunity of being of service.

Sincerely,

George C. Wiswell, Jr., P.E.  
President

UNDERWATER SERVICES  
CONSULTING  
ENGINEERING

SOIL SURVEYS  
CONDITION REPORTS

MAINTENANCE  
REPAIR

# TABLE OF CONTENTS

	<u>Page</u>
Table of Contents.....	ii
Figures and Photographs.....	iii
Abstract.....	iv
Introduction.....	v
Section 1 Background.....	1
Section 2 Existing Pile Jackets.....	3
Section 3 Underwater Inspection.....	6
Section 4 Pile-Pile Cap Connections.....	8
Section 5 Fender Systems.....	9
Section 6 Batter Piles.....	10
Section 7 Assessment of Structural Integrity.....	11
Section 8 Assessment of Repairability.....	14
Section 9 Cost and Time Estimate.....	19
Section 10 General Site Conditions.....	21
Section 11 Pile Data Background.....	22
Appendix I Pile Data & Calculations.....	A- 1
Appendix II Pile Inspection Data Bents #2 thru #50.....	A- 8
Appendix III Pile Inspection Data Bents #51 thru #81.....	A-18
Appendix IV Ultrasonic Thickness Data.....	A-26
Appendix V Government Furnished Information.....	A-42
Appendix VI Petrographic Examination, Findings.....	A-43
Appendix VII Photographs.....	A-47



Distribution/	
Availability Codes	
Dist	Avail and/or Special
A-1	

## FIGURES AND PHOTOGRAPHS

	<u>PAGE</u>
Figure #1 Concrete Jacket Design	16
Figure #2 Alternate Piling Repair	17
Photo #1 Wiswell, Inc. Employees	A-47
Photo #2 Getting to work	A-47
Photo #3 Southerly view on Pier Lima	A-48
Photo #4 View of G Row from west side access ramp	A-48
Photo #5 Closer view of G Row	A-48
Photo #6 View of A Row looking shoreward	A-49
Photo #7 Typical pile cap damage	A-49
Photo #8 Bent #37, Pile F	A-50
Photo #9 Separated joint on west access ramp	A-50
Photo #10 Section between Bents #15 & 16	A-51
Photo #11 Cracks radiating outwards from flange	A-51
Photo #12 Bent #77, Pile F	A-51
Photo #13 Bent #81, Pile F	A-52
Photo #14 Bent #81, Pile G	A-52
Photo #15 Batter pile between Bents #71 & #72	A-53
Photo #16 Batter pile between Bents #67 & #68	A-53
Photo #17 Bent #44 (not 45), Pile G	A-54
Photo #18 Batter between Bents #37 & #38	A-54
Photo #19 Bent #57, Pile F	A-55
Photo #20 Bent #55, Pile F	A-55
Photo #21 Bent #47, Pile F	A-55
Photo #22 Improperly filled form	A-56
Photo #23 Destroyed fender pile	A-56
Photo #24 Spalling adjacent to flange edge	A-57
Photo #25 View of 90 pound concrete sample	A-57
Photo #26 Close up under jacket	A-58
Photo #27 Bent #16, Row F	A-58
Photo #28 Bent #15, Row G	A-58
Photo #29 Bent 40, Row A	A-59
Photo #30 Bent #40, Row A	A-59
Photo #31 Bent #40, Row B	A-59
Photo #32 Mudline photograph	A-60
Photo #33 Cleaned section of web	A-60

#### ABSTRACT

Structural assessment and repairability of the steel "H"-piles supporting Pier Lima, Naval Station, Guantanamo Bay, Cuba are presented. Field data gathering techniques included underwater ultrasonics, underwater and above surface visual inspection and measurement, still photography, and underwater television. Areas of inspection included existing pile jackets, detailed underwater inspections of piles, pile-pile cap connections, and the existing fender system.

Analysis was conducted using field data and government-furnished information. Scope of work was limited to assessment of piles on singular basis, with pier system comments and conclusions included in general terms.

The pier was found to have only approximately half of its original capacity. Re-jacketing most of the piles with concrete jackets, re-securing pile-pile cap connections, and installation of a new fender system and batter piles is recommended as a cost-effective repair to bring the pier to approximately 90 percent of its original capacity.

## INTRODUCTION

This report is the final product of the engineering services, provided by Wiswell, Inc. to assess the structural condition and repairability of the structural steel "H"-piles supporting Pier Lima at the Naval Station, Guantanamo Bay, Cuba. This assessment includes underwater inspection and documentation, assessment of available past inspection data and drawings of the pier and other Government furnished information, engineering calculations, and the determination of repair techniques including a cost and time estimate for the repairs to be made.

This assessment was conducted under Contract No. N62477-79-C-0387 with the Department of the Navy, Chesapeake Division, Naval Facilities Engineering Command through the Ocean Engineering and Construction Project Office. Wiswell, Inc. personnel conducted onsite inspections from July 31 thru August 3, 1979. The objective of this project is to assess the structural condition and repairability of the steel "H"-piles supporting Pier Lima. To accomplish this assessment, inspections were made of existing pile jackets, underwater conditions of the steel "H"-piles, pile-pile cap connections, and the fender system. The information gathered on the conditions encountered is presented in the text of the report and in Appendices I, II, III, IV, VI, and VII.

#### BACKGROUND

A detailed underwater inspection was conducted of Pier Lima, Guantanamo Bay, Cuba from July 30 thru August 3, 1979. This inspection included a detailed ultrasonic inspection of some 16 piles as well as basic inspection of the remaining piles in the structure. Also inspected was the pile deck itself, fender pile system, and other factors contributory to the integrity of the structure.

After the piles to be inspected, using ultrasonics were chosen, the piles were cleaned at three elevations. These elevations were directly under the pile jacket, at the mudline, and at a distance approximately half way between these two locations. At each elevation the piles were cleaned of biofouling and oxidation down to clean metal. This cleaning was done on one flange and one side of the web at each location with additional cleaning of the opposite flange at the upper elevation. This cleaning was done for a band 6 inches to a foot wide. This cleaning allowed not only an accurate visual inspection of the structural steel but also allowed a clean, corrosion-free surface for the ultrasonic testing.

Once the pile had been cleaned the diver/engineer would inspect the pile. The pile inspection consisted of both visual, tactile, and ultrasonic evaluation. Visually each cleaned elevation of each pile was inspected for pits, deformations, holes, and any deterioration or abnormalities. The growth surrounding the cleaned area was inspected and in most cases additional growth scraped off to determine the nature and consistency of biofouling and oxidation. The piles were then measured.

Measurements were primarily conducted using the ultrasonic non-destructive test unit, but included the depth measurements of any pits that were located using a pit gauge or the ultrasonic unit. If it was possible to get the transducer into the pit, holes were also measured using a conventional

steel rule and thicknesses of the flange were measured and verified using a caliper device.

Ultrasonic measurements were taken in the entire cleaned area prior to a specific measurement being taken. This enabled the diver/engineer to have an understanding of the area being measured as well as knowledge of the exact location to be measured in detail. A total of 15 readings were taken at each pile consisting of seven readings just under the pile jacket, four readings at a mid-depth location, and four readings at a mudline location. In each case a series of readings were taken and a mathematical average of the readings computed as the mean thickness value for that specific location. It has been found that this method allows a much more accurate representation of the pile being inspected.

It is interesting to note that most pits had a steel thickness of .25 inches to .35 inches while the area around the pits was usually .42 inches to .47 inches. This was found to be true in most areas with medium or deep pits.

Some abnormal conditions were noted on certain piles in that very large, deep pits were discovered that were very pronounced. These pits were by themselves and went almost completely through the pile. A number of holes were also discovered which had probably originated as one of the deep pits. In most cases these deep pits and holes were located only at the upper elevation directly under the pile jacket, except for one hole located just above the mudline.

Upon completion of the detailed inspection of the 16 piles, photographic documentation and video tape recordings of the inspection techniques as well as conditions encountered were made.



#### EXISTING PILE JACKETS

There were basically four types of existing pile jackets at Pier Lima. The first was an older-style short jacket consisting of a very coarse concrete, 3 to 4 feet in length with a diameter of 24 inches. The second was the newer-style tall jacket approximately 6 feet long and 28 inches in diameter with a concrete of a very fine texture. The third consisted of jackets primarily located in the outer bents of the pier which had cardboard Sonotube forms still in place which were approximately 6 feet in length containing a concrete with a very coarse aggregate. The fourth type of jackets found were two square jackets of fine grain concrete and two jackets made with 55 gallon drums.

The short, older-style pile jackets ranged in length from 3 feet to 3 1/2 feet long and consisted of a very coarse grain concrete. The diameter of the jackets was found to be 24 inches. The aggregate used in this concrete was varied and might possibly have contained shells. The present condition of these jackets is very deteriorated. The top and bottom sections of these jackets are cracking and spalling at the flange corners due to the corrosive action of the piles. It would appear that the steel piles were not cleaned enough prior to the coal tar epoxy application to seal out the moisture from the piles. Once the moisture had entered, a corroding action began which then cracked the concrete pile jacket. In some cases this forced portions of the jacket off the pile completely. Signs of this type of deterioration were noticed on a majority of the piles as noted in the appendix. It was noted that large amounts of aggregate were exposed in the concrete at the waterline, suggesting either a cold joint or the leaching out of cement from the concrete due to a sulfate attack at one time. It was also noted that there did not appear to be as much exposed aggregate around the other types of jackets. Also, on the shorter-style jackets,

it was noted that the bottoms of the jackets were highly irregular and in many cases sections of the jacket had fallen away with as much as 1 foot of the jacket missing. The taller newer-style jackets were found to be in better condition than the older-style jackets. These jackets had a height of approximately 6 feet with some as long as 8 feet. On the average they had 4 feet above the water surface and 2 feet of it extending below the water surface with a diameter of 28 inches. The concrete in these jackets was a fine grain concrete which appeared in very good condition. Most of these piles had only one or two very small cracks generating from the end of the flange outward in the cylinder to the outer circumference of the pile jacket.

The third type of jacket inspected was the Sonotube-type jackets. These concrete jackets were still encompassed by the fiberboard Sonotube that was used as a form. Inspection of the actual concrete was limited due to this coverage but in many spots where the concrete was available for inspection it was noted that an abundance of large aggregate was present with little concrete showing. If these locations were points that were leaking concrete during construction, this condition would be quite possible. Without knowledge of the concrete used it is difficult to determine the strength of these repairs. The Sonotube jackets were approximately 6 feet to 8 feet long and with the exception of a select few were in good condition. It should be noted that the exceptions in most cases were caused by improper support of the form allowing the form to lose concentricity, allowing it to fall over and completely block concrete from getting into the opposite side. This would not allow adequate cover around the steel H-pile.

The remaining type of jackets found under the pier were square jackets which were both 24 inches square and approximately 6 feet long, consisting of a fine grain concrete which appeared to be in good condition and of good quality. Also two jackets were found formed with 55 gallon drums.

During our inspection of the pile jackets, the amount and type of cracks and spalls were noted and are included in the appendix. In most cases small spalling cracks approximately 1/16" to 1/8" wide had generated from the flange edge radially outward to the outer circumference of the pile jackets. In the worst cases, notably the short older-style jackets this deterioration had progressed enough to allow actual spalling of concrete. This condition was caused due to the improper protection of the upper portion of the steel H-pile as well as a possible improper cleaning of the H-pile inside the concrete jacket, allowing water entry and the corrosive action. Another fault discovered in the inspection was that of the lack of concentricity of pile jackets. To effectively protect and strengthen the steel H-piles, the pile jacket must remain concentric about the axis of the pile. On many piles this was not the case. When the concrete pile jacket does not have adequate cover over the steel pile, it both reduces the structural strength given to that pile as well as allowing moisture to seep back to the steel pile and allow the corroding process to begin. On many piles inspected rust signs were readily observable. Unfortunately, the GFI could not include all records of the past repairs made to this pier. Therefore, the time frame in which the smaller older-style repairs were made is not known nor is there data on the concrete used for the four types of pile jackets. Due to the inability to inspect the concrete of those piles that were encased in Sonotubes, structural conclusions are based on small portions of the concrete inspected through occasional opened sections. Further inspection including concrete coring should be conducted on these piles, during the repair phase, to further evaluate these piles.

### UNDERWATER INSPECTION

We feel that the underwater inspection of the 16 piles portrayed a representative sample of the piles under the pier and allowed conclusions to be made on the conditions to be encountered on all piles in general. Several piles were chosen due to the GFI identification as having "DW" or decreased flange width. Both prior to and after cleaning these piles, the corrosion of the flanges was apparent. After the cleaning, the exact extent of the corrosion was determined and noted. Several slides were taken of the conditions encountered at each of the three inspection elevations.

In most cases, the flange deterioration or "necking down" of the flange was found at the upper elevations only. In most cases, this necking down was located within 2 feet of the underside of the pile jacket which would be between 2 feet and 4 feet below the water surface. Loss of section of the flange was contained within a specific zone on each pile. There were no lengthy sections of severe loss. It was found that within a foot of this elevation, the pile flange once again was at original width with a flange thickness at the edge of 1/8" to 3/16".

Conditions encountered at the upper elevation usually consisted of large deep pits with either knife edge flanges or scalloped flange edges. Biofouling was heavy at this elevation although soft and easily removed. Steel oxidation was present under the biofouling in two layers. The outer most layer was removed easily and was gray in color, the final oxidation level was very hard and had to be forcibly removed and being black in color. Pitting at this elevation varied from smooth steel with a few deep pits to a pattern of small and medium pits very close to each other creating a rippled effect.

Conditions encountered at the mid-depth elevation differed from the upper elevations in that no loss of flange section was evident and fewer large pits were encountered. Biofouling

was reduced substantially while the two oxidation levels were basically the same as the upper elevation.

The mudline elevation inspection showed no loss of flange section, very little biofouling, and the oxidation was found to adhere more to the steel pile. Pitting at this elevation usually consisted of a tight pattern of small and medium pits over the entire surface.

The corrosion of steel in sea water has been found to be 0.005" to 0.010" per year, under normal conditions. However, an accelerated, non-uniform type of attack, commonly called pitting can occur. It seems to be generally accepted that weight loss of submerged steel appears to be an increasing function with respect to time. The pitting factor decreases with respect to time, so the longer the exposure, the lower the pitting factor. This pitting factor can double or triple the weight loss in a specific area over a period of ten years. Due to the limited area of severe pitting, effects of pitting in a structural analysis of submerged steel piles is difficult. An over-all knowledge of the extent of pitting and location of most severe pitting is required, and even then, conclusions remain only estimates. (Ref. Hosford)

At Pier Lima the average rate of section loss was 0.185 square inches per year at the elevation below the present concrete jackets. This is drawn from an average remaining cross-sectional area of 16.1 square inches (or 75 percent of original) after 29 years of exposure. It should be noted again that the rate of corrosion has been increasing with time and will continue to increase. These above mentioned sections do not, however, include the pitting factor which would further decrease the remaining section by as much as 15 percent. Due to the random locations of pits their effects can be factored in directly, but must be considered in the final analysis.

#### PILE-PILE CAP CONNECTIONS

During our inspection it was noted that several piles were not carrying any load and that several piles were not connected to the pile cap. In the case of piles not carrying any load, gaps ranged from mere fractions to as much as  $\frac{3}{4}$  of an inch. Some of these piles were held in position by bolts or lag screws while others were free to move and were observed doing so with the wave action. In some cases the pile plate was noticeably unparallel to the pile cap. In the cases where only partial bearing was achieved, the transfer of load from the deck to the pile when a live load was applied would be questionable. Upon loading, the combination of angled pile plate and partial bearing would cause the pile to displace sideways out from under the pile cap. Fasteners used in securing the pile plates to the pile cap varied considerably from spikes to bolts to lag screws to sections of rebar. In many cases bolts were present but loose. When transferring a lateral load such as ship impact, these loose bolts rather than acting in sheer, would act in tension and would allow failure of the fastener. In some cases, fasteners were only an inch or two from the outer face of the pile cap which would allow the failure of the timber prior to estimated yield. The bearing area of many of the piles were found to be less than 50 percent. In these cases, although a portion of the pile plate was in direct contact and secured to the pile cap, the central axis of the H-pile did not go through the pile cap. Depending on loads exerted to the pier, this circumstance could greatly reduce the actual capacity allowable for these piles.

#### FENDER SYSTEM

An inspection of the fender system on Pier Lima showed that all piles were suffering from Limmoria attack and had a reduced cross section at the waterline of at least 50 percent. Many piles were broken at the waterline and some piles only existed from the mudline to the water surface, with the top portion missing. Some brand new piles were in position on the northeast end of the pier.

Due to the apparent heavy Limmoria infestation and the requirement of adequate fenders, the fender system must be rebuilt and/or redesigned. While conducting our survey two fender piles, one old and one new, were broken in half during berthing operations. If the timber fenders are ineffective, loads will be taken by the pier structure directly. One concrete-jacketed H-pile was found to have been displaced due to an impact and paint chips were still on the concrete jacket.

### BATTER PILES

The batter piles were found to be in poor condition. Many batter piles had splices installed at the same elevation of the top level of the concrete jackets which created a very weak structural situation. The splices consisted of two plates bolted to opposite flanges, which resulted in the cross sectional area and strength of the pile being weakest at this location. Also noted was that only a few batter piles had adequate concrete coverage over the H-piles. In most cases, the steel was covered by one inch or less of concrete. The necessity of installing splices on these batter piles reflects that problems were encountered at one time with the structural strength of these piles. Unfortunately, the repairs made to these piles did not adequately protect and strengthen the weak areas. The installation of additional batter piles appears necessary although replacement of all batter piles is not called for.



#### ASSESSMENT OF STRUCTURAL INTEGRITY

It is the opinion of this firm and its principals that Pier Lima, at Guantanamo Bay, Cuba, should be immediately downrated and ship activity restricted. We feel that the data developed herein supports this decision and explains the necessities for this recommended action. Several factors were considered in the structural assessment. The average minimum cross sectional area of piles was determined to be 78 percent, resulting in the average pile capacity being reduced to 52 percent. This value could be further reduced by as much as 15 percent on specific piles that have holes and severe deep pitting at the elevation under the concrete jacket. This "pitting factor" was also considered as an additional variable in the assessment. (Ref. Rogers)

The majority of the piles have the small older-style jackets which are of questionable benefit. These jackets appear to have temporarily restricted the corrosion of the piles they encase, but not protect or fully strengthen them. The spalling of these jackets, both topside and underwater, demonstrates that this repair was improperly designed and constructed. The length of the jackets is inadequate to encompass the normal zone of deterioration which is evident by the flange width loss directly below these jackets.

The connections between the pile plates and the pile caps were also inspected and factored into the assessment. There exists over 150 piles which require new bolts and installations, over 60 piles which need realignment, and at least 12 piles that require shimming to properly transfer any pier load. At least 5 sections of pile cap were deteriorated enough to necessitate replacement or reinforcing. These conditions, taken by themselves are not as critical. Coupled with the pile deterioration and lack of functional fender system they become significant.

The existence of holes through the flanges and webs in the existing H-piles, combined with the existence of large, deep pits in the H-piles prompted careful study of the piles to determine their structural strength and repairability. This deterioration was primarily located in the area directly beneath the smaller older-style jackets, which constituted the weakest area of the piles. However, due to the localized nature of the severe deterioration, the piles are repairable. Calculations of pile capacity yielded values of 38 to 57 percent of their original capacities, or maximum loads of 48 to 119 kips. As mentioned earlier, heavy pitting, flange corrosion, and the existence of holes could lower these values an additional 15 percent.

The batter piles, as they presently exist, offer a fraction of their original capacity due to the method of splicing and jacketing. The jackets, while covering what is suspected to be the area of worst deterioration, does not consist of a proper structural repair due to the absence of adequate concrete cover over existing steel. This fact combined with the splice locations above the jacket, makes this the weakest point in the pile. Under a load, the two parallel plates would not offer proper restraint and a deformation of the plates would occur and indeed has occurred in at least two piles. Rather than replace all batter piles we suggest replacing strategically located batter piles, so positioned to provide proper lateral restraint to the pier where the lateral loads would occur during a berthing operation and under wind loads.

Due to these conditions we suggest a temporary downrating of Pier Lima to 250 pounds per square foot. The derivation of this value is outlined in Appendix I. This rating should remain in effect until the suggested repairs are made and further evaluation and rating of the Sonotube encased piles has been completed.

Although the scope of work has not included a complete pier system structural analysis, some general conclusions can be drawn from the site conditions coupled with the calculations presented. Continued berthing activity without an adequate fender system will allow all vessel impacts to be directly transferred to the steel piles. In their present condition, pile failure is quite possible during a heavy lateral impact load.

Prior to the installation of a new fender system caution should be exercised in all berthing operations so as not to allow any significant impact load. The effectiveness of the present fender design should be re-evaluated with respect to both cost and effective life prior to timber piles being replaced.

We suggest restricting berthing activities until a new fender system has been installed. Restrictions should include additional caution exercised in berthing operations and all vessels should be tug-assisted. Tugs should avoid any contact with the timber fender piles if possible. During undocking operations two fender piles were sheared in half due to the force a tugboat exerted on it. Extra caution should be taken when winds are over 15 knots when any vessel is being berthed.

## ASSESSMENT OF REPAIRABILITY

1. PILE JACKETS All of the small older-style jackets should be removed and replaced. In most cases these jackets are presently cracked in the area of each flange, making removal not difficult. Due to the uncertain concrete strength, numerous cracks and spalling occur both above and below the waterline, so the jackets do not effectively add strength to the piles. If these jackets were left on, they would continue to deteriorate and offer less and less structural strength.  
The pile jackets that replace these should be longer jackets, approximately 8 feet long, to encompass all of the heavy deterioration of the piles. These jackets should contain a reinforcing bar cage as shown in the attached engineering drawing and should be of proper 5000 psi concrete. After installation of the pile jacket, the exposed steel pile between the pile cap and the new pile jacket should be sandblasted to commercial finish and a coal tar epoxy applied.  
An alternate method of repair would involve bolting two sections of MC 10 x 28.5 steel into the webs of the corroded steel H-piles. Each pair of channels would be bolted in place with ten (10) stainless steel bolts of 7/8 inch diameter. This method of repair is represented in Figure 2.  
Due to the necessity of thorough cleaning of the steel piles and the thinness of the pile in the area to be repaired, this method, although an acknowledged repair method, is not recommended. Furthermore, the extent of corrosion of the steel at this location leads us to recommend concrete as an appropriate repair material over steel.
2. PILE CAP CONNECTION The repairs necessary to bring the pile-pile cap connections to their original design

capabilities include:


- (a) New bolt installations. Presently spikes and lengths of rebar are securing the piles and these should be replaced with proper lag screws or bolts, where applicable, to securely fasten the piles to the pile caps. As mentioned before there are approximately 150 piles requiring this repair.
- (b) Shimming of the piles. The shimming of piles that are presently not carrying a load is required. Due to the present configuration this would best be achieved by jacking up the cap in that location and installing spacers or shims. There are approximately 12 piles that require this repair.
- (c) Repositioning piles. There are approximately 60 piles that presently do not properly line up with the pile cap. These piles must either be forcibly repositioned after bolts through the pile cap have been removed, or if necessary larger pile plate installed and additional timber pile cap pieces installed to allow the pile to bear more effectively on the pile cap system.
- (d) Repairs to the deteriorated pile caps. There are at least five pile cap sections which are deteriorated enough to allow possible failure of the pile cap. Repair of these timbers could be accomplished either by removing a section, replacing it, and securing this new section to the existing timber pile cap splicing the two together with a splice plate and bolts. An alternate would be to form around the existing timber and inject an epoxy resin/fungicide that would not only strengthen the piece but also halt any further rot or decay. The locations for this work are at the ends of the pile caps offering good accessibility.

3. FENDER SYSTEM The fender system as it exists now is ineffective. As mentioned before, either a timber fender system or a rubber, marine fender system should be installed to absorb any lateral loads such as ship impact or wind loads.

If a timber fender system is to be reinstalled, protection of the piles from Limmoria attack is desirable. Various manufacturers of heavy plastic wrap such as Pile Guard or Zippertubing have systems which cause stagnant water to be trapped around the timber thereby destroying worms attempting to attack the timber. Although this plastic wrap cannot withstand ship abrasions, we feel that an adequate protection system of walers would be adequate to protect the plastic wrap from damage.

An alternate fender system would consist of Lord/Bridgestone-type marine fender which would not require any timber fender piles but would rely on the compressive nature of the rubber fenders and the pier structure itself for absorbing any impact.

After the recommended repairs have been completed the pier, with the exception of those piles with the Sonotube forms still in place, would achieve 100 percent of its design capacities. As stated before, those piles with Sonotube forms require further analysis in the form of concrete cores taken of a representative sample of piles. Depending on those results, the pier would be rated at its full design capacity.






FIGURE 2  
ALTERNATE PILE REPAIR  
BY INISWELL INC



### COST AND TIME ESTIMATE

Estimates for both cost and time required to complete the repairs have been computed for the above recommended repairs. Due to the geographical location and associated logistics problems of transporting men, equipment, and necessary supplies, estimates are based on men and equipment departing from Norfolk, Virginia on government-provided transportation. The repairs to each pile consisting of removal of the old jacket, cleaning of the piles, installing the reinforcing cage, forming the pile, pumping it with a high strength concrete and application of the coal tar epoxy is estimated to be \$1,158.30 per pile. This price consists of:

Concrete Forms	\$ 140.00
Hydro-Laser for cleaning	60.00
Misc. material & equipment	90.00
Labor, overhead & profit	<u>868.30</u>
	\$1,158.30

Based on 518 piles to be jacketed, the total for this repair would be \$600,000. We recommend the jacketing of a minimum of 335 piles with an option for more piles to be jacketed, as individually inspected. The minimum cost would be \$388,030.50, based on the \$1,158.30 per pile. These price estimates are realistic and competitive and in our opinion, the lowest responsible bid would be very close to this figure. The length of time required to complete this repair would be approximately six to eight months.

The repairs to the pile-pile cap connections include the new bolt installations, the shimming of the piles not presently carrying a load, jacking piles into alignment, and the repair of deteriorated pile caps. This work has been estimated at a cost of \$200,000 and would require two months to complete. An estimate for the fender system was difficult to compile due to transportation, etc., of the materials, equipment, etc. It was noticed, however, that a large supply of treated timber piles were present at the base. We feel that a Naval

operation of replacing the timber piles would be more cost effective than an outside contractor doing this work. The cost for wrapping the timber piles is estimated at \$250 per pile. This wrapping would have to be conducted prior to installation of the waler protection system. The cost for the Lord/Bridgestone marine fender system is estimated at \$200,000.

The estimate assumes concrete to be supplied, without cost, by the U.S. Navy batching plant located on the Naval Station. Additionally, housing is to be supplied, without cost, by the U.S. Navy at the Naval Station.

These repairs should extend the useful life of Pier Lima an additional 15 to 20 years, with 100 percent of its original capacity. The 100 percent capacity is contingent on the further inspection of the jackets with forms remaining, which could be easily factored into the repair contract.

#### GENERAL SITE CONDITIONS

During the inspection it was noted that the tidal flux was minimal, averaging less than a foot. In discussion with personnel at the site, it was determined that the prevailing wind was from the northwest which would be coming off the shore in the area of Pier Lima.


It was also determined that the location of Pier Lima relative to the harbor entrance made it a very busy pier as far as ship activities were concerned.

Pier Lima was originally constructed as a timber pier with a dry dock on the west side. The older timber piles were replaced by steel piles in the size of BP 12x53 and BP 14x73 in the early 1950's. 232 of these piles were then jacketed to some extent in the early 1970's. These jackets are referred to in the text as the long, newer-style jackets. No data was available on the dates or details of the jackets on the remaining piles, which were protected with three different types of jackets.

The specifications for the early 1970's repairs call for four types of jackets to be used, depending on the deterioration. Reference is made to holes in piles, flanges missing and remaining areas of less than 50 percent. Some 135 piles required the more extensive repairs.

We must assume that in view of the generally poor condition of some of these jackets that this deterioration has continued and is now more severe than at that time.

# PILE DATA BACKGROUND



$$I = \frac{BH^3 + bh^3}{12}$$

$$S = \frac{I}{C} = \frac{BH^3 + bh^3}{6H}$$

$$r = \sqrt{\frac{BH^3 + bh^3}{12(BH + bh)}}$$

$$A = BH + bh$$

$K = 1.0$ , assuming top of pile not fixed or braced.

$$l = h = 10' + (\text{mudline to waterline}) + (\text{waterline to cap})$$

To calculate the moment of inertia, section modulus, and radius of gyration for the piles inspected in detail, certain assumptions had to be made. The average flange thickness was taken as the mathematical average of the values taken at each elevation. The web thickness was taken as the mathematical average of the web thickness readings at each elevation.

The flange width offered a problem in that the knife edge shape of the flange as it approached the end made it difficult to get a realistic width measurement. In many cases, there was a scalloped effect where it was readily ascertainable that the width was decreased. In each case where the scalloping occurred the flange width approximated 12.5 inches. These cases were only found at the upper elevation, beneath the pile jacket. In those cases where a knife edge was still present the flange width was slightly more but due to the extreme thinness of the flange, we have opted to assume a flange width of 12.5 inches for all readings taken just below the underside of the jacket. For readings taken at mid-depth and at mudline there was no loss of steel at the flange edges and the knife edge effect

was much less pronounced, therefore, a flange width of 14.5 inches was used.

APPENDIX I

PIER LIMA  
NAVAL STATION, GUANTANAMO BAY, CUBA

PILE CAPACITY DATA & CALCULATIONS

PILE CAPACITY DATA

PIER LIMA  
GUANTANAMO BAY, CUBA

<u>PILE/LOCATION</u>		<u>A<sub>s</sub></u> (in. <sup>2</sup> )	<u>A<sub>s</sub></u> <u>A<sub>o</sub></u> (%)	<u>K<sub>1</sub></u> <u>F</u>	<u>F<sub>a</sub></u> (kips)	<u>P</u> (kips)	<u>P<sub>o</sub></u> (kips)	<u>P</u> <u>P<sub>o</sub></u> (%)
14G	UJ	14.44	67.3	134.3	8.23	119.0	240.	49.6
	- 8'	16.10	75.0					
	-16'	17.82	83.0					
15F	UJ	15.22	70.9	150.0	6.64	101.0	220.	45.9
	- 8'	18.37	85.6					
	-18'	19.22	89.6					
15G	UJ	16.25	75.7	169.1	5.22	80.5	153.	52.6
	-15'	15.42	71.8					
	-25'	18.26	85.1					
16G	UJ	16.38	78.3	169.1	5.22	80.5	153.	52.6
	-15'	18.02	84.0					
	-25'	17.90	83.4					
37E	UJ	17.27	80.5	193.2	4.00	65.8	123.	53.5
	-19'	18.54	86.4					
	-30'	16.46	76.7					
37F	UJ	16.70	77.8	193.8	3.98	66.5	123.	54.0
	-17'	18.69	87.1					
	-30'	17.00	79.2					
37G	UJ	15.56	72.5	215.9	3.10*	48.2*	100.	48.2*
	-20'	16.52	77.0					
	-35'	18.73	87.3					
40A	UJ	16.20	75.5	195.1	3.93	63.7	123.	51.8
	-18'	17.80	82.9					
	-30'	18.53	86.3					
40B	UJ	15.00	69.9	187.8	4.24	63.6	128.	49.7
	-18'	19.21	89.5					
	-29'	16.40	76.4					
40C	UJ	14.31	66.6	192.9	4.01	51.0	134.	38.1
	-19'	12.72	59.3					
	-28'	18.14	84.5					
40D	UJ	16.77	78.1	181.2	4.55	76.3	134.	56.9
	-19'	18.07	84.2					
	-28'	18.86	87.9					

PILE CAPACITY DATA  
(page 2)

PILE/LOCATION		$A_1$ (in. <sup>2</sup> )	$\frac{A_1}{A_o}$ (%)	$\frac{Kl}{r}$	$F_a$ (ksi)	P (kips)	$P_o$ (kips)	$\frac{P}{P_o}$ (%)
40E	UJ	16.54	77.1	195.8	3.90	64.5	123.	52.4
	-20'	18.34	85.5					
	-30'	17.12	79.8					
40F	UJ	15.71	73.2	201.3	3.70*	58.3*	108.	54.0*
	-21'	18.85	87.8					
	-33'	19.51	90.9					
40G	UJ	17.74	82.7	201.3	3.70*	61.5*	108.	57.0*
	-20'	16.62	77.4					
	-33'	19.74	92.0					
79F	UJ	16.60	77.4	198.6	3.79	62.9	118.	53.3
	-15'	16.83	78.4					
	-31'	16.64	77.4					
79G	UJ	16.08	74.9	210.8	3.40*	54.7*	100.	54.7*
	-17'	17.54	81.7					
	-35'	17.87	83.3					

\*Due to value of  $\frac{Kl}{r}$  exceeding 200, extrapolation necessary to determine allowable stress.

KEY:

$A_1$  = Cross sectional area  
 $A_o$  = Original cross sectional area  
 $F_a$  = Allowable stress  
P = Pile capacity (kips)  
 $P_o$  = Original pile capacity (kips)  
 $\frac{Kl}{r}$  = Effective slenderness ratio

Note: Factor of Safety = 1.67

Note: Pile is non-compact



PILE DATA

PIER LIMA  
GUANTANAMO BAY, CUBA

Pile/Location		A (in.)	B (in.)	C (in.)	I (in. 4)	S (in. 3)	R (in.)
14G	UJ	.363	.426	12.5	118.0	18.9	2.86
	- 8'	.371	.424	14.5	188.6	26.0	3.42
	-16'	.423	.441	14.5	215.0	29.6	3.47
15F	UJ	.368	.478	12.5	120.0	19.2	2.80
	- 8'	.445	.434	14.5	226.2	31.2	3.51
	-18'	.481	.418	14.5	244.5	33.7	3.57
15G	UJ	.443	.411	12.5	144.3	23.1	2.98
	-15'	.353	.411	14.5	179.4	24.7	3.41
	-25'	.449	.416	14.5	228.2	31.5	3.53
16G	UJ	.447	.413	12.5	145.6	23.3	2.98
	-15'	.457	.378	14.5	232.2	32.0	3.59
	-25'	.444	.399	14.5	225.6	31.1	3.55
37E	UJ	.453	.472	12.5	147.6	23.6	2.92
	-19'	.443	.452	14.5	225.2	31.1	3.48
	-30'	.375	.443	14.5	190.6	26.3	3.40
37F	UJ	.433	.466	12.5	141.0	22.6	2.91
	-17'	.433	.487	14.5	220.1	30.4	3.43
	-30'	.399	.431	14.5	202.8	28.0	3.45
37G	UJ	.400	.441	12.5	130.3	20.8	2.89
	-20'	.407	.374	14.5	206.8	28.5	3.54
	-35'	.476	.391	14.5	242.0	33.4	3.59
40A	UJ	.415	.462	12.5	135.2	21.6	2.89
	-18'	.454	.368	14.5	230.7	31.8	3.60
	-30'	.442	.453	14.5	224.7	31.0	3.48
40B	UJ	.398	.401	12.5	129.6	20.7	2.94
	-18'	.469	.445	14.5	238.4	32.9	3.52
	-29'	.371	.448	14.5	188.6	26.0	3.39
40C	UJ	.345	.451	12.5	112.4	18.0	2.80
	-19'	.256	.420	14.5	130.1	17.9	3.20
	-28'	.450	.404	14.5	228.7	31.5	3.55
40D	UJ	.457	.424	12.5	148.8	23.8	2.98
	-19'	.437	.428	14.5	222.1	30.6	3.50
	-28'	.464	.429	14.5	235.8	32.5	3.54
40E	UJ	.421	.477	12.5	137.1	21.9	2.88
	-20'	.447	.427	14.5	227.2	30.3	3.52
	-30'	.420	.392	14.5	213.5	29.4	3.53
40F	UJ	.431	.392	12.5	140.4	22.5	2.98
	-21'	.454	.451	14.5	230.8	31.8	3.50
	-33'	.465	.478	14.5	236.4	32.6	3.48

FILE DATA  
(page 2)

Pile/Location	$\bar{A}$ (in.)	$\bar{B}$ (in.)	$\bar{C}$ (in.)	$\bar{I}$ (in. <sup>4</sup> )	$\bar{S}$ (in. <sup>3</sup> )	$\bar{r}$ (in.)
40G UJ	.485	.446	12.5	158.0	25.3	2.98
-20'	.395	.410	14.5	200.8	27.7	3.47
-33'	.481	.460	14.5	244.5	33.7	3.52
79F UJ	.430	.464	12.5	140.1	22.4	2.90
-15'	.390	.438	14.5	198.2	27.3	3.45
-31'	.411	.375	14.5	208.9	28.8	3.54
79G UJ	.433	.417	12.5	141.0	22.6	2.96
-17'	.422	.421	14.5	214.5	29.6	3.51
-35'	.422	.447	14.5	214.5	29.6	3.46

KEY:

A = Mean Flange Thickness  
 B = Mean Web Thickness  
 C = Flange Width  
 I = Moment of Inertia  
 S = Section Modulus  
 r = Radius of Gyration

### DEAD LOAD CALCULATIONS

Pier - 60' x 648' = 38,880 sq. ft.

Reinforced concrete with aggregate @ 150#/cu. ft.

Long Leaf Yellow Pine @ 44#/cu. ft.

Old Concrete Deck 8" thick = 25,920 cu. ft. = 3,888 kips

New Concrete Deck 8 1/2" thick = 27,540 cu. ft. = 4,131 kips

Concrete Curb 30" x 10" x 525' = 1,093.75 cu. ft. = 164 kips

Concrete Skirt 12" x 24" x 555' = 1,110 cu. ft. = 166.5 kips

Combined Deck = 8,349.5 kips

Pile Caps - composite made up of 6" x 12" and 12" x 12"  
plus 6" x 16" and 14" x 16"

18" x 12" = 1.5 sq. ft.

20" x 16" = 2.22 sq. ft.

3.72 sq. ft.

x 60' = 223.2 cu. ft./bent x 44#/cu. ft. = 9,820.2#/bent

x 80 bents = 785,664# = 785.7 kips

#### Recap:

8,349.5

+ 785.7

9,135.2 kips ÷ 81 bents (including #1 (shore)) = 112.8 kips/bent

÷ 7 piles/bent (unweighted re spacing) = 16.11 kips/pile

#### Spacing between pile rows as follows:

A to B 12.5'

D to E 9.5'

B to C 9'

E to F 8.5'

C to D 8.5'

F to G 8.25'

#### This spacing arrangement yields the following loading:

<u>ROW</u>	<u>LOAD PER ROW</u> <u>(kips)</u>	<u>LOAD PER PILE IN THE ROW</u> <u>(kips)</u>
A	1,256	15.4
B	1,636	20.2
C	1,332	16.4
D	1,370	17.0
E	1,372	17.0
F	1,256	15.6
G	912	11.2

\*Assumes combined dead load of 9,136 kips

# LIVE LOAD CALCULATIONS

<u>PILE/LOCATION</u>	<u>P</u> <u>(kips)</u>	<u>P<sub>i</sub></u> <u>(kips)</u>	<u>D</u> <u>(kips)</u>	<u>L</u> <u>(kips)</u>
14G	119.0	72.3	11.2	61.1
15F	101.0	61.3	15.6	45.7
15G	80.5	48.9	11.2	37.7
16G	80.5	48.9	11.2	37.7
37E	65.8	40.0	17.0	23.0
37F	66.5	40.4	15.6	24.8
37G	48.2	29.3	11.2	18.1
40A	63.7	38.7	15.4	23.3
40B	63.6	38.6	20.2	18.4
40C	51.0	31.0	16.4	14.6
40D	76.3	46.3	17.0	29.3
40E	64.5	39.2	17.0	22.2
40F	58.3	35.4	15.6	19.8
40G	61.5	37.3	11.2	26.1
79F	62.9	38.2	15.6	22.6
79G	54.7	33.2	11.2	22.0

## Key:

P = pile capacity (safety factor = 1.67)

P<sub>i</sub> = pile capacity (safety factor = 2.75)

L = live load capacity (safety factor = 2.75)

D = dead load for that pile, in that bent

Pier - 60' x 648' = 38,880 sq. ft.

Pier area per pile =  $\frac{38,880 \text{ sq. ft}}{81 \times 7} = 68.57 \text{ sq. ft}$

Live Load Capacity(L) = Pile Capacity(P or P<sub>i</sub>) - Dead Load(D)

Minimum value for live load = 14.6 kips on Pile 40C

Live Load =  $\frac{14.6 \text{ kips/pile}}{68.57 \text{ sq ft/pile}} = 213 \text{ p.s.f.}$

The recommended live load capacity is 250 pounds per square foot. This value allows a safety factor of more than 2.5, without greatly restricting pier operations. In our judgment and based on the pile capacity calculations, downrating the pier to 250 p.s.f. is a safe operating load.

**APPENDIX II**

**PIER LIMA  
NAVAL STATION, GUANTANAMO BAY, CUBA**

**PILE INSPECTION DATA  
BENTS #2 THRU #50**

FILE #		BOLTS	BEARING AREA	JACKET	CRACKS	SPALLS	COMMENTS
2	A		G				
	B		G	O			DC, ER
	C		G				
	D		G				
	E	2	G				NJ
	F		G				
	G		G				
	BP						
3	A	2	G	O			
	B	2	G	N			*
	C	2	G	O			
	D	2	G	O			
	E	2	G				55 gallon drum
	F	2	G				
	G	2	G				55 gallon drum
	BP						
4	A						
	B						
	C						
	D						
	E						
	F						
	G						
	BP						
5	A			N-4	1H		
	B	1		N-4	3H		
	C			O-2	3S		
	D			O-2		1MS	
	E			O-2			
	F			O-2			
	G			O-2	1S		
	BP						** , NJ
6	A			N-4	1H		
	B	1		N-4	1H		GC
	C			O-2	2S		
	D			O-2	2S		
	E	2		O-2			
	F	2		O-2	1S		
	G	2		O-2	3S		
	BP						
7	A			N			A, PP
	B			O	4S, 1h	1SS	A
	C			Sq			***
	D					2MS	DC, ER, BS
	E	2		O	-		
	F	2		O	-		
	G						
	BP						

\*Appears to have buckled and failed.

\*\*Cut off one foot above waterline.

\*\*\*Note--electrical vault located between 7C and 7D.

PILE #		BOLTS	BEARING AREA	JACKET	CRACKS	SPALLS	COMMENTS
8	A	2		N	2S		A*
	B	2		O	3S		A
	C	2		Sq			
	D	2				1MS	
	E	2			2S		
	F	2			3S		
	G	2			2S		
	BP						**
9	A	2		N	1H		
	B	2		N	2S		V
	C	2		O	2S		
	D	2		O	-		DC
	E	2		O	2S		
	F	2		O	3S		
	G	2		O	3S		
	BP						**
10	A	2		N	2S		
	B	2		N	1S		A, DC
	C	2		O	1H		DC
	D	2		O	1S, 1H		
	E	2		O	4S		
	F						
	G						
	BP						
11	A	1		N	1S		
	B	2		N	1S		GC
	C			O-1		1SS	A
	D	2		O	1S		
	E	2		O	2S		
	F	2		O	-		
	G	2		O			
	BP						**
12	A	1			1H		
	B	1	50		1S		PC
	C				3S		
	D	2		O	5S		
	E	2			3S		
	F						V
	G						GC
	BP						
13	A	2			3S		
	B						
	C	2			1S		
	D				3S		HC
	E	2		O			GC
	F	2		O	1S		
	G	2		O		1SS	
	BP						

\*Note--between Bent #6 and #8 there are 4 plumb piles and 4 batter piles, old-type repairs, on westside of pier.

\*\*Batter pile cut off one foot above waterline.



<u>PILE #</u>		<u>BOLTS</u>	<u>BEARING AREA</u>	<u>JACKET</u>	<u>CRACKS</u>	<u>SPALLS</u>	<u>COMMENTS</u>
14	A	2			3S	1SS	ER
	B	2			4H		
	C	2		O	1S		DC, HC
	D	2		O	3S		PC
	E	2		O	-		
	F	2		O	-		A
	G	2		O	-		
	BP						
15	A	2		N	1H		PP
	B				3S		RS
	C	2			1S		RS, A, HC
	D				1S		DC
	E	2			2S		
	F	2			-		
	G	2			-		
	BP						
16	A	R			3S		DC
	B	2			3S		
	C	2			1H		
	D				3S		
	E	2					
	F	2			2S		
	G						
	BP						
17	A	2	G	N-3	3S		ER
	B	2	G	N-3	H, S		DC
	C	2	G	O-2	1S		
	D	2	G	O-2	1S		
	E	2	G	O-2	-		
	F	1	G	O-2	4S		PC
	G	2	G	O-2	4S		DC
	BP			N-4.5		1MS	1 1/2" cover
18	A	2	G	N-3	2S		DC, Pdet.
	B	2	G	N-3.5	2S		
	C	2	G	O-2			
	D	2	G	O-2	3S		
	E	2	G	O-2.5	3S		
	F	1	G	O-2	2S		PC
	G	2	G	S-4			
	BP						
19	A	2	G	N	3S		ER
	B	2	G	N-3	1H		RS
	C	2	G	O-2	4S	1MS	
	D	2	G	O-2.5	4S		
	E	2	G	O-2.5	3S		
	F	1	85	O-2	3S		PC
	G	None	G	N-4.5	1S		
	BP				2S		1" cover

PILE #	BOLTS	BEARING		JACKET	CRACKS	SPALLS	COMMENTS
		AREA					
20	A	None	G	N-3.5			DC
	B	2	G	N-3.5			DC
	C	2	G	O-2			
	D	2	G	O-2	3S		RS
	E	2	G	O-2.5	3S		RS
	F	R	85	O-2	2S		
	G	None	90	N-4.5	3S		
	BP					2MS	3/4" cover
21	A	2	G	N-3	1S		ER
	B	2	G	O-2	4S		PC
	C	2	G	O-2	1H		
	D	2	G	O-2	4S		DC
	E	1	G	O-2	3S		BS
	F		N	O-2	3S		BS
	G	2		N-4	1H		BS
	BP						No cover, fallen
22	A	2	G	N-3	3S		DC
	B	2	G	O-2	1H	1MS	RS
	C	2	G	O-2	4S		DC
	D	2	G	O-2.5	1S	2MC	
	E	2	G	O-2.5	4S		BS, PC
	F	2	G	O-2	3S	1MS	BS
	G	2	95	N-4.5	2S	2MC	DC
	BP						1" cover
23	A	2	G	N-3	1S		PP
	B	2	G	O-2	5S		MC, BS
	C	2	G	O-2	2S		BS
	D	2		O-2	4S		BS
	E	2	G	O-2		1MS	BS
	F	1	30	O-2	4S		DC
	G	1	75	N-4			
	BP					4MC	1" cover, PP
24	A	2	G	N-4		3MC	BS, ER, RS
	B	2	G	O-2		3MC	BS, DC
	C	2	G	O-2	3S		RS, BS
	D	2	G	O-2	4S		BS, PC
	E	2	G	O-2	4S		BS
	F	R	70	O-2		3MC	BS
	G	1	80	N-4			PP
	BP					1MC	1/2" cover
25	A	2	80	S-3			
	B	2	G	O-2	3S		BS
	C	2	G	O-2	4S		BS
	D	2	G	O-2.5		4MC	BS
	E	2	G	O-2.5	1S	1MC	
	F	None	G	O-2		3MC	PD, BS
	G	None	G	O-4			PP, BS, DC
	BP			N			1" cover

PILE #		BOLTS	BEARING AREA	JACKET	CRACKS	SPALLS	COMMENTS
26	A	2	G	N-3	2S, 1h		DC, BS
	B	2	G	N-3	1H		ER, RS
	C	2	G	O-2	3S, 1H		BS
	D	2	G	O-2	5S	1MS	
	E	2	G	O-3	3S		BS
	F	S	G	O-2.5		4MC	RS, BS
	G	R	G	N-4	1H		PP, DC
	BP						
27	A	2	G	N-3	4S		GC
	B	2	G	N-3.5	1H		RS, HC
	C	2	G	O-2.5	3S	1MS	RS
	D	2	G	O-2		4MC	RS, BS
	E	2	G	N-4	1S		GC
	F	None	G	O-2		1MS	PD, twisted, RS, ER, BS
	G	None	40	N-4	1H, 1S		PP
	BP						
28	A	2	G	S-3			
	B	2	G	S-2			
	C	2	G	O-2	1S		
	D	2	G	O-2	3S	2MS	PC, HC
	E	2	G	O-2	4S		
	F	R	80	O-2		1MS	2" cover, BS
	G	None	90	N-4	2S		PP, PC
	BP						V, DC
29	A	2	G	N-4	3S		V, RS
	B	1	G	O-2		5MC	
	C	2	G	O-2	2S		ER
	D	2	G	O-2.5	3S, 1H		ER
	E	2	G	O-2	4S, 1h		
	F	R	G	O-2	3S		
	G	None			3S	1MS	No cover
	BP						
30	A	1	60	N-4	1S		GC
	B	1	G	O-2	4S		
	C	2	G	O-2.5	2S, 2H		BS
	D	2	G	O-2	2S	1MS	ER
	E	2	G	O-2	3S, 1H		ER
	F	S	70	O-2	3S		BS
	G	1	90	S-4			MC
	BP						1 1/2" cover
31	A	1	G	N-2	3S, 1h		
	B	1	80	S-3			
	C	2	G	O-2	1S		
	D	2	G	O-2	4S, 1h		3S, HC
	E	2	G	O-2	4S		ER, BS
	F	1	70	O-2	4S		
	G	1	G	N-4.2	1H		
	BP						V (large), bad splice

FILE #	BOLTS	BEARING		JACKET	CRACKS	SPALLS	COMMENTS
		AREA					
32	A	None	G	N-4	5S, 2H		PC
	B	None	80	N-2	2S		DC, HC, RS
	C	2	G	O-2	2S		
	D	2	G	N-3	2S		
	E	1	G	O-2	4S		ER, DC
	F	1	80	O-2	3S		RS, DC
	G	1	60	N-4	1S, 1H		DC, PP
	BP						PP, MC
33	A	2	G	N-3.5	2S		H, A, PP, RS
	B	1	G	O-2	3S		BS
	C	2	G	O-2	4S		DC
	D	2	G	O-2	3S		RS, PC
	E	2	G	O-2	4S	1MS	BS
	F	None	50	O-2	4S	1MS	
	G	2	G	N-4			
	BP					1MS	1" cover
34	A	2	G	N-4	2S		A, HC
	B	S	50	S-2	4S		DC
	C	2	G	S-2	3S		
	D	2	G	S-2	4S, 1H		RS, DC
	E	2	80	S-2		4MC, 1MS	close to F row
	F	R	80	S-2	4S		HC
	G	2	60	N-4	1H		H
35	A	2	G	N-3	5S, 1h		DC, PP
	B	S	90	O-2	1S		MC
	C	2	G	O-2	3S, 1h		DC
	D	2	G	Sq-3	1H		
	E	2	G	O-2	4S		HC
	F	None	50	O-2	3S		ER
	G	R	G	N-4.5	1H		DC
	BP						1" cover
36	A	None	G	N-2	3S		
	B	1	60	O-2	2S		BS
	C	2	G	O-2	1S, 1H		BS
	D	2	G	O-2	4S		PC
	E	2	G	N-3.5	2S		RS
	F	None	50	O-2	4S		A, H, PC
	G	None	G	S-4			MC
	BP				1S, 5H		MC, ER
37	A	2	G	N-3.5	3S, 1h		PP
	B	1	60	O-2	2S	1MS	
	C	2	G	O-2	3S		BS
	D	2	G	O-2		2MS	HC
	E	2	G	O-2	3S		BS
	F	None	30	O-2	3S	1MS	
	G	1	G	N-4	4H		PP
	BP				4S		Bad splice (bent)

PILE #	BOLTS	BEARING		JACKET	CRACKS	SPALLS	COMMENTS
		AREA					
38	A	2	G	N-5	1H		
	B	2	40	O-2	4S		PC
	C	2	G	O-2	3S		DC
	D	2	G	O-2	4S		HC
	E	2	G	O-2	4S		BS
	F	R	G	O-2	2S	1MS	
	G	None	50	N-3			GC, MC
	BP						
39	A	S	G	N-4			GC
	B	None	G	O-2	4S	1MS	RS
	C	2	G	N-6	1H		
	D	2	G	O-2		4MC	BS
	E	2	G	O-2		2MS	PD, 30% jacket off, HC
	F	None	G	O-2		4MC	BS
	G	1	N	N-4			1/2" cover, PP
	BP				4S		1/2" cover, PP
40	A	R	90	N-4			PP
	B	2	G	O-2.5	2S	2MC	
	C	2	G	O-2	3S		
	D	2	G	O-2	4S		ER
	E	2	G	O-2	4S		BS
	F	None	40	O-2	4S		ER, BS
	G	None	25	S-3.5			
	BP				3S		1 1/2" cover, PP
41	A	R	G	N-4	1H, 1h		GC
	B	1	G	O-2	2S		DC
	C	2	G	O-2	3S		DC
	D	2	G	O-2	5S	1MS	RS, HC
	E	2	G	N-3.5	2S		PP
	F	2	90	N-4			ER
	G	1	50	N-3.5	3S		
	BP				3S		1/2" cover
42	A	S	G	S-4.5			Pdet, BS
	B	2	G	O-2		4MC	BS
	C	2	G	N-3.5			PP
	D	2	G	O-2	4S		RS, DC
	E	2	G	O-2	4S		BS, HC
	F	None	G	N-4	1H		PP
	G	None	10	S-4			Pdet
	BP						
43	A	R	G	N-4	4S		PP
	B	R	G	O-2	4S	1MS	
	C	2	G	O-2	3S		HC, DC
	D	2	G	O-2		4MC	HC
	E	2	G	N-3.5	5S	1MS	HC
	F	None	50	N-4	1S, 2h		
	G	1	65	N-4			PP
	BP				5SP		3/4" cover, DC

PILE #		BOLTS	BEARING AREA	JACKET	CRACKS	SPALLS	COMMENTS
44	A	R	G	N-4	3S		Pdet, ER, DC
	B	R	G	N-4.5			RS, PP
	C	2	G	O-2	4S		
	D	2	G	O-2	4S		DC, HC
	E	2	G	O-2	4S	1MC	HC, DC, BS
	F	R	G	N-4	2S, 1h		ER, 1" cover
	G	None	N	S-4			
	BP				2S		MC
45	A	R	G	N-5	1S		PP
	B	None	G	N-5			GC
	C	2	G	O-2	4S		DC
	D	2	G	O-2	4S	1MC	HC
	E	2	G	O-2	4S	1MS	HC
	F	2	90	N-3.5	3S		ER, MC
	G	2	80	N-4	1S		ER
	BP				2S		3/8" cover, flange exposed
46	A	S	G	N-6	1H		PP
	B	None		O-2	4S	2MS	DC
	C	2	G	O-2	4S, 1h		
	D	2	G	O-2	4S, 1h		HC
	E	2	G	N-4	3S, 1h		1" cover
	F	R	75	O-2	4S	2MS	Pdet, HC
	G	1	85	S-3.5			70% jacket gone
	BP						
47	A	S	G	N-5			Pdet, GC
	B		G	O-2	4S		
	C		G	O-2	2S		
	D		G	O-2		1MS, 4MC	HC
	E		G	O-2	3S	2MS	
	F	None	G	O-2	4S	1MS, 1MC	
	G	None	35	N-4.5	3S		DC
	BP				4S, 1h		MC, PP
48	A	None	G	N-5			GC
	B		G	O-2	3S	1MS	RS
	C		G	O-2	4S, 1h		
	D		G	O-2	4S		DC, RS, HC
	E		G	O-2	4S		DC
	F	R	G	O-2	4S		DC
	G	S	G	S-3.5			Fallen, no cover
	BP				2S		No cover, fallen, PP
49	A	S	20	N-5	2S		DC
	B	None	G	N-4	3S		
	C		G	S-4.5			
	D		G	O-2	4S		MC, HC
	E		G	O-2	4S		DC
	F	R	G	O-2	4S		RS, HC
	G	None	N	N-4	3S		Pdet
	BP				3S		3/4" cover, PP

<u>PILE #</u>		<u>BOLTS</u>	<u>BEARING AREA</u>	<u>JACKET</u>	<u>CRACKS</u>	<u>SPALLS</u>	<u>COMMENTS</u>
50	A	2	G	S-4			
	B	1	G	O-2	4S		DC
	C	2	G	O-2	4S		DC
	D	2	G	O-2	5S		RS, HC
	E	2	G	O-2.5	4S, 1h		HC, DC
	F	None	G	O-2	4S, 1h		HC, DC
	G	S	N	S-4			
	BP						

GLOSSARY OF SYMBOLS  
FOR  
BENTS #2 THRU #50

Fasteners

2.....2 bolts  
1.....1 bolt  
S.....Spike  
R.....Rebar  
-.....Not applicable

Bearing

G.....100%  
N.....None  
20.....20%

Jacket

S.....Sonotube  
O.....Old style  
N.....Long new style  
Sq.....Square (24")  
-2.....2' height above waterline

Cracks

1S.....1 spall crack  
1H.....1 hairline crack  
1h.....1 horizontal crack

Spalls

1 MC.....1 major spalling crack  
1 MS.....1 major spall  
1 SS.....1 small spall

Comments

GC.....Good concrete  
PC.....Poor concrete  
ER.....Rebar exposed  
G.....Jacket in good condition  
DC.....Deteriorated concrete  
HC.....Heavy corrosion just above jacket  
A.....Pile is angled 5° or more  
PP.....Powdery/porous concrete  
RS.....Rust stains in concrete jacket  
PD.....Pile previously displaced  
P Det.....Pile cap deteriorating  
BS.....Bottom of jacket spalling  
MC.....Minimal coverage of concrete  
H.....Hole in pile  
NJ.....Not jacketed  
V.....Voids in concrete  
1" cover.....1" coverage of concrete over steel



APPENDIX III

PIER LIMA  
NAVAL STATION, GUANTANAMO BAY, CUBA

PILE INSPECTION DATA  
BENTS #51 THRU #81

FILE NO.	DBJ	JT	MFC	DAB	PPCC	BC	COMMENTS
56	A	N	S	2	A	N	N
	B	N	R	N	N	N	N
	C	N	R	N	N	N	N
	D	N	O	2	A	N	N
	E	N	R	N	N	N	N
	F	N	R	N	N	80	P
	G	N	R	N	N	N	N
	GB	N					
							Jacket cracked along flange
							10° twist
							Heavy pitting below jacket, bent flange
57	A	N	R	N	A	N	P
	B	N	R	N	N	N	N
	C	A	R	N	N	N	N
	D	N	O	N	A	N	N
	E	A	O	N	A	N	N
	F	A	O	N	A	50	P
	G	N	R	N	N	N	N
	AB	N	R	N	N	N	N
							10° twist
							Jacket cracked along flange
							Jacket cracked along flange
							Jacket cracked along flange
58	A	N	S	1	N	N	P
	B	N	R	N	N	N	N
	C	N	R	N	A	N	N
	D	A	O	N	A	N	N
	E	N	R	N	A	N	N
	F	A	R	1	A	75	P
	G	N	R	<1	A	N	N
	GB	N	R	N	A	N	N
							flange exposed below surface
							20° twist
							Pitted below jacket
59	A	N	R	N	N	N	P
	B	N	R	N	N	N	N
	C	N	R	N	N	N	N
	D	A	O	2	A	N	N
	E	N	O	<1	A	N	N
	F	A	R	N	A	50	P
	G	N	R	2	A	N	N
	AB	N	R	2	N	N	N
							Jacket cracked along flange
							Bad jacket deterioration
							20° twist
60	A	A	S	<1	N	N	N
	B	A	R	N	N	N	N
	C	A	O	N	A	N	N
	D	N	R	N	N	N	N
	E	A	O	N	A	N	N
	F	N	R	N	A	N	P
	G	A	R	1	N	N	N
	GB	N	R	2	N	N	N
							1" flange hole below jacket, JC
							Bad pitting on web below jacket

<u>PILE NO.</u>	<u>DBJ</u>	<u>JT</u>	<u>MFC</u>	<u>DAB</u>	<u>PPCC</u>	<u>BC</u>	<u>COMMENTS</u>
61	A	A	S	2	N	N	N
	B	N	S	1	N	N	N
	C	A	R	1	N	N	N
	D	A	R	2	N	N	N
	E	N	R	N	A	N	N
	F	N	R	N	A	50	P
	G	N	R	N	A	N	N
	AB	N	R	2	N	N	N
							Two 3" jacket holes exposing flange Pitting below jacket
62	A	N	S	1	N	N	N
	B	A	R	1	N	N	N
	C	A	R	N	N	N	N
	D	A	R	N	N	N	N
	E	A	R	N	A	N	N
	F	N	R	N	A	90	N
	G	N	S	1	A	50	P
	GB	A	R	2	A	N	N
							10° twist Failed flange above jacket 1-1/2" notch in flange 10° twist Pitted webbing below jacket
63	A	A	S	1	N	N	N
	B	N	S	2	N	80	N
	C	A	S	<1	N	N	N
	D	N	S	1	N	N	N
	E	N	S	1	N	80	N
	F	A	S	2	N	50	U
	G	A	S	N	A	10	P
	AB	N	R	<1	N	N	N
							Old adjacent pile replaced File not vertical Jacket pouring incomplete, PL Jacket cracked along flange
64	A	N	S	1	N	N	N
	B	N	S	N	N	80	N
	C	N	S	2	N	70	N
	D	N	S	2	N	N	N
	E	A	S	N	N	N	P
	F	N	S	1	A	40	N
	G	A	S	2	A	N	N
	GB	N	R	1	N	N	N
							Old adjacent pile replaced Old adjacent pile replaced
65	A	N	S	<1	N	N	N
	B	N	S	N	N	N	N
	C	A	S	N	N	N	N
	D	N	S	2	N	N	N
	E	A	S	2	N	N	N
	F	N	S	N	A	50	U
	G	A	R	N	A	N	N
	AB	A	R	2	A	N	N
							10° twist Old adjacent pile replaced 10° twist 4" necking below jacket

PILE NO.	DBJ	JT	MFC	DAB	PPCC	BC	COMMENTS
66	A	N	S	<1	N	N	20° twist
	B	N	S	N	N	N	2" hole in flange
	C	N	S	N	N	N	
	D	N	S	N	N	N	
	E	N	S	N	N	N	
	F	N	S	2	A	30	10° twist
	G	N	S	2	A	N	Hour glass below jacket
	GB	N	R	<1	N	N	Spliced 3/4" bolts thru 1" hole
67	A	N	S	<1	A	N	
	B	A	S	N	N	N	10° twist, bad pitting
	C	A	S	1	N	N	5° twist
	D						
	E	A	S	N	N	N	
	F	N	S	1	N	N	
	G	A	S	N	A	N	
	AB	N	R	N	N	N	
68	A	N	S		A	N	Jacket cracked at flange, 10° Twist
	B	N	S	N	N	90	10° twist
	C	N	S	N	N	N	
	D	N	S	A	N	N	
	E	N	S	N	N	N	
	F	N	S	A	N	N	
	G	N	S	2	A	N	
	GB	N	R	2	N	N	
69	A	N	S	2	N	N	10° twist
	B	N	S	2	N	80	20° twist
	C	A	S	N	N	N	15° twist
	D	N	S	N	N	N	
	E	A	S	N	N	N	
	F	N	S	A	N	N	15° twist
	G	A	S	1	N	N	
	AB	N	R	N	N	N	
70	A	N	S	2	N	N	Tilted pile with 25% cap contact
	B	N	S	1	N	N	
	C	N	S	N	N	N	
	D	N	S	N	N	N	
	E	N	S	A	N	N	aggregate visible on jacket
	F	N	S	N	75	N	15° twist
	G	N	S	N	N	N	
	GB	N	R	2	N	N	

FILE NO.	DBJ	JT	MFC	DAB	PPCC	COMMENTS		
51	A	N	R	N	A	80	P	
	B	N	S	N	N	10	U	Broken brace
	C	A	O		A	N	N	One side jacket missing
	D	N	O		A	N	N	Two sides missing, flange bent
	E	N	S	<1	N	N	N	10° twist
	F	A	O	N	A	40	U	JC, HP, NJ
	G							
	AB	A	R	1	A	N	N	
52	A	N	R	N	N	90	P	20° twist
	B	N	S	2	N	N	N	
	C	A			A	N	U	No jacket
	D	N			A	80	U	No jacket
	E	N	S	<1	A	N	P	
	F	N	R	2	N	80	N	10° twist
	G	N						
	GB	N						Pitted below jacket
53	A	N	R	N	N	N	P	
	B	A	R	N	N	90	N	Cap pile partially broken, HP
	C	N	S	N	N	N	N	
	D	N	O	N	A	N	N	Jacket cracked along flange
	E	N	O	N	A	N	N	Jacket cracked along flange
	F	N	R	N	N	N	N	
	G	N						
	AB	N	R	N	N	N	N	Jacket cracked along flange
54	A	N	S	R	N	50	P	Cap pile deterioration
	B	N	O	N	N	N	N	Jacket cracked along flange
	C	A	O	N	A	N	N	Jacket cracked along flange
	D	N	R	N	N	N	N	
	E	N	O	N	A	N	N	Jacket cracked along flange
	F	N	O	N	A	90	N	Jacket cracked along flange, T-10°
	G	N						Heavy pitting below jacket
	GB	N						
55	A	N	R	N	A	60	P	Cap pile deteriorated, T-10°
	B	N	R	N	N	N	N	
	C	N	R	N	N	N	N	
	D	N	O	2	A	N	N	Jacket cracked along flange
	E	N	O	<1	A	N	N	Bad jacket deterioration
	F	A	R	N	N	60	U	
	G	N						
	AB	N	R	1	N	N	N	

PILE NO.	DBJ	JT	MFC	DAB	PPOC	BC	COMMENTS
71	A	N	S	N	N	N	10° twist
	B	N	S	N	N	N	
	C	N	S	N	N	P	
	D	N	S	N	N	N	
	E	A	S	N	N	N	
	F	N	S	N	50	P	
	G	N	S	1	N	P	Aggregate visible
	AB	N	R	N	N	N	
72	A	N	S	1	N	N	Pitted below jacket
	B	N	S	N	N	N	
	C	N	S	N	N	N	
	D	N	S	N	N	N	
	E	N	S	N	N	N	
	F	N	S	A	50	P	
	G	N	S	1	A	50	P
	AB	N	R	2	N	N	20° twist
	GB	N	R	0	A	N	
73	A	N	S	1	A	20	20° twist
	B	A	S	N	N	N	
	C	N	S	N	N	75	
	D	N	S	N	N	N	
	E	N	S	N	N	N	
	F	N	S	N	N	N	
	G	N	S	A	50	P	
74	A	N	S	2	N	90	10° twist, adjacent pile replaced
	B	N	S	1	N	N	
	C						
	D	N	S	N	N	N	
	E	N	S	N	75	P	
	F	N	S	N	10	P	
	G	N	S	<1	N	N	
	AB		R	<1	A	N	
	GB	N	R	2	N	N	
75	A	A	S	2	N	N	
	B	N	S	2	N	N	20° twist
	C	N	S		N	N	
	D	N	S		N	N	
	E	A	S		N	N	
	F	N	S		N	P	
	G	A	S		N	40	Hour glass below jacket

<u>PILE NO.</u>	<u>DBJ</u>	<u>JT</u>	<u>MFC</u>	<u>DAB</u>	<u>PPOC</u>	<u>BC</u>	<u>COMMENTS</u>
76	A	N	S	N	N	N	
	B	A	S	2	N	90	N
	C	N	S		N	N	N
	D	A	S		N	N	N
	E	N	S		N	N	N
	F	N	S		N	10	U
	G	N	S	1	N	50	P
	AB	N	R	N	N	N	N
	GB	N	R	1	N	N	N
77	A	N	S	<1	N	O	P
	B	N	S	N	N	N	N
	C	A	S		N	N	N
	D	N	S		N	N	N
	E	A	S		N	O	U
	F	N	S	<1	N	50	P
	G	N	S		N	N	N
78	A	N	S	1	N	N	N
	B	N	S	1	N	N	N
	C	N	S		N	N	N
	D	N	S		N	N	N
	E	A	S		N	N	N
	F	A	S		N	80	N
	G	N	R	O	N	N	N
	AB	N	R	2	N	N	N
	GB	N	R	1	N	N	N
79	A	N			A	N	N
	B	A	S	1	N	N	N
	C	A	S		N	80	N
	D	N	S		N	50	P
	E	N	S		N	80	N
	F	A	S		N	N	N
	G	N	S		N	N	N
	AB	N	R	2	N	N	N
	GB	N	R	1	N	N	N
80	A	N			N	N	N
	B	N	S	2	N	N	N
	C						
	D						
	E	A	S		N	N	N
	F	A	S		N	N	N
	G	N	S		A	N	N
	AB	N	R	2	N	N	N
	GB	N	R	1	N	N	N

<u>FILE NO.</u>	<u>DBJ</u>	<u>JT</u>	<u>MFC</u>	<u>DAB</u>	<u>PROC</u>	<u>BC</u>	<u>COMMENTS</u>
81	A	A		A	90	P	No jacket
	B	N	S	N	N	N	
	C	A		N	75		
	D	N	S	N	N	N	
	E	N	S	N	N	N	Hole in webbing 3' below jacket
	F						
	G	A	S	N	N	P	
	AB	N	R	2	N	N	
	GB	A	R	2	N	N	Hole in web at cap



GLOSSARY OF SYMBOLS  
FOR  
BENTS #51 THRU #81

BJD.....Below jacket deterioration  
A.....Accelerated  
N.....Normal

JT.....Jacket type  
S.....Sonotube  
R.....Regular  
O.....Old style

MFC.....Minimum flange coverage  
N.....Normal  
2.....2"  
1.....1"

DAB.....Deterioration above jacket  
A.....Accelerated  
N.....Normal

PPCC.....Percentage pile cap coverage  
N.....Normal

BC.....Bolt Connection  
P.....Partial  
N.....Normal  
U.....Unattached

NJ.....No jacket  
T-10°.....Twist in pile 10°  
HP.....Heavy pitting below jacket  
JC.....Jacket cracked along flange  
PL.....Partial loss of jacket

APPENDIX IV

PIER LIMA  
NAVAL STATION, GUANTANAMO BAY, CUBA

ULTRASONIC THICKNESS DATA

WISWELL, INC.


U.S. NAVAL BASE GUANTANAMO BAY, CUBA, PIER LIMA

DATE: 7/31/79 BENT # 14 ☒ PLUMB ☐ BATTER PILE # G

CONDITION OF CAP: \_\_\_\_\_


CONDITION OF JACKET: \_\_\_\_\_

ULTRASONIC READING: A. 0.402 C. 0.425 E. 0.418 G. 0.365  
 ELEV: 6" Under Jacket  
 C - Large Pits  
 E - Large pits  
 F - Large pits  
 G - Large pits




A.	0.402	C.	0.425	E.	0.418	G.	0.365
	.430		.425		.418		.308
	.457		.424		.417		.307
	.459		.425		.418		.291
	.457		.425		.418		.297
	.417		.425		.421		.268
	.450		.426		.416		.306
			.425		.415		.307
Av.	0.439	Av.	0.426	Av.	0.418	Av.	0.306
B.	0.316	D.	0.427	F.	0.441		
	.317		.450		.450		
	.317		.459		.324		
	.326		.439		.326		
	.317		.424		.324		
	.316		.424		.418		
	.317		.425		.436		
	.321		.429		.397		
Av.	0.318	Av.	0.435	Av.	0.390		

ELEV: -8' Pnemo  
 B - Many shallow pits



A.	0.392	B.	0.383	C.	0.436	D.	0.402
	.370		.389		.436		.402
	.388		.387		.436		.402
	.370		.383		.435		.408
	.382		.321		.458		.409
	.402		.312		.473		.405
	.370		.314		.440		.408
			.388		.439		.406
Av.	0.382	Av.	0.360	Av.	0.444	Av.	0.405

ELEV: -16' Pnemo  
 Note: opposite side  
 F - some pitting



D.	0.433	E.	0.418	F.	0.480	G.	0.465
	.432		.410		.481		.457
	.432		.412		.481		.458
	.430		.416		.378		.457
	.431		.415		.331		.457
	.432		.416		.378		.458
	.433		.415		.425		
	.433				.429		
Av.	0.432	Av.	0.415	Av.	0.423	Av.	0.459

COMMENTS, CALIBRATIONS: .488

GENERAL PIER CONDITION: Note: Supposedly 12" HP-53

WISWELL, INC.

U.S. NAVAL BASE GUANTANAMO BAY, CUBA, PIER LIMA


DATE: 7/31/79 BENT # 15 ☒ PLUMB ☐ BATTER PILE # F

CONDITION OF CAP: \_\_\_\_\_

CONDITION OF JACKET: \_\_\_\_\_

ULTRASONIC READING:

ELEV: 8" Under Jacket




A - All large  
Pits

Also large  
pits between B.  
D & E

G - Consider-  
able pitting

A.	0.196	C.	0.495	E.	0.488	G.	0.440
	.189		.496		.474		.362
	.223		.495		.478		.354
	.221		.461		.467		.363
	.213		.461		.449		.431
	.204		.462		.449		.412
	.189		.471		.455		.379
	.307		.472		.457		.393
Av.	0.218	Av.	0.477	Av.	0.465		0.391
	.444	D.	0.494	F.	0.432		
	.446		.492		.433		
	.442		.494		.407		
	.443		.481		.446		
	.433		.497		.472		
	.434		.498		.403		
	.436		.497		.420		
	.434				.406		
Av.	0.433	Av.	0.493	Av.	0.427		


ELEV: -8' (pneumo)



Calibration  
.488  
.489

A.	0.450	B.	0.502	C.	0.470	D.	0.418
	.452		.504		.472		.418
	.454		.414		.474		.418
	.463		.413		.475		.417
	.459		.412		.418		.421
	.466		.412		.417		.432
	.413		.418		.418		.417
	.453						.417
Av.	0.451	Av.	0.439	Av.	0.449	Av.	0.420

ELEV: -18' (pneumo)



A.	0.481	B.	0.481	C.	0.411	D.	0.426
	.487		.489		.408		.428
	.438		.491		.410		.427
	.490		.489		.411		.425
	.481		.490		.414		.426
					.412		.425
							.425
Av.	0.475	Av.	0.488	Av.	0.411	Av.	0.426

COMMENTS, CALIBRATIONS:

Pit gauge showed pits at elev. under jacket as follows: @ A 0.320 between D & E 0.240

GENERAL PIER CONDITION: Note: Supposedly 12" HP-53

WISWELL, INC.

U.S. NAVAL BASE GUANTANAMO BAY, CUBA, PIER LIMA


DATE: 7/31/79 BENT # 15 ☒ PLUMB ☐ BATTER PILE # G

CONDITION OF CAP: \_\_\_\_\_

CONDITION OF JACKET: \_\_\_\_\_

ULTRASONIC READING:

ELEV: 6" Under Jacket




A - Large pits  
pit gauge  
.310  
.295

G - Large pits  
1 1/2"  
diameter  
Pit Gauge  
.330

A.	0.457	C.	0.475	E.	0.415	G.	0.449
	.436		.443		.416		.451
	.435		.441		.415		.457
	.438		.425		.415		.469
	.435		.433		.416		.457
			.435		.415		.452
							.453
							.452
	Av. 0.440		Av. 0.442		Av. 0.415		Av. 0.455
B.	0.457	D.	0.378	F.	0.437		
	.456		.378		.451		
	.465		.373		.418		
	.465		.368		.401		
	.432		.369		.413		
	.457		.370		.438		
	.452		.371		.427		
	.456		.373				
	Av. 0.455		Av. 0.378		Av. 0.425		


ELEV: -15' Pneumo



B - Large pits

A.	0.357	B.	0.326	C.	0.425	D.	0.395
	.357		.307		.425		.396
	.355		.316		.425		.395
	.412		.355		.426		.396
	.358		.356		.425		.396
	.357		.357		.426		.395
	.369		.353		.427		.396
			.356		.426		.398
	Av. 0.366		Av. 0.341		Av. 0.426		Av. 0.396

ELEV: -25' Pneumo



A.	0.442	B.	0.442	C.	0.425	D.	0.408
	.441		.459		.425		.404
	.448		.444		.423		.402
	.450		.455		.432		.405
	.460		.437		.426		.405
	.457		.438		.428		.407
	.457		.438		.430		.405
			.464		.428		.403
	Av. 0.451		Av. 0.447		Av. 0.427		Av. 0.405

COMMENTS, CALIBRATIONS: \_\_\_\_\_

GENERAL PIER CONDITION: \_\_\_\_\_

Note: Supposedly 12" HP-53

WISWELL, INC.

U.S. NAVAL BASE GUANTANAMO BAY, CUBA, PIER LIMA

DATE: 7/31/79 BENT # 16 ☒ PLUMB ☐ BATTER PILE # G


CONDITION OF CAP: \_\_\_\_\_

CONDITION OF JACKET: \_\_\_\_\_

ULTRASONIC READING:

ELEV: 6" Under Jacket


C - Pits  
.200 deep



G - Caliper  
check .450

A.	0.457	C.	0.433	E.	0.415	G.	0.430
	.480		.458		.417		.435
	.485		.462		.415		.433
	.429		.433		.417		.431
	.437		.457		.421		.431
	.457		.450		.407		.431
	.402		.472		.417		.432
	.410		.401		.417		
Av.	0.445	Av.	0.446	Av.	0.416	Av.	0.432
B.	0.502	D.	0.376	F.	0.427		
	.482		.375		.426		
	.483		.376		.433		
	.484		.375		.428		
	.488		.378		.425		
	.489		.380		.426		
	.459		.378				
Av.	0.484	Av.	0.377	Av.	0.426		


ELEV: -15'



See  
Below

A.	0.442	B.	0.459	C.	0.386	D.	0.370
	.448		.465		.385		.370
	.443		.460		.383		.371
	.457		.465		.386		.370
	.455		.463		.386		.373
	.452		.488		.392		.380
	.451		.462		.378		.370
	.452		.461				.371
Av.	0.450	Av.	0.465	Av.	0.385	Av.	0.372

ELEV: -25'



A.	0.444	B.	0.432	C.	0.443	D.	0.354
	.450		.430		.444		.360
	.449		.431		.444		.363
	.453		.437		.454		.356
	.457		.432		.433		.355
	.449		.449		.446		.354
	.441		.450		.426		.361
	.451		.450		.428		.359
Av.	0.449	Av.	0.439	Av.	0.440	Av.	0.358

COMMENTS, CALIBRATIONS: Internal test = 0.200 Test block = 0.490

At 1" from edge of flange near "A" .412, .416, .418, .417, .415

GENERAL PIER CONDITION: \_\_\_\_\_

Note: Supposedly 12" HP-53

U.S. NAVAL BASE GUANTANAMO BAY, CUBA, PIER LIMA

CONDITION OF CAP:

CONDITION OF JACKET:

A. 0.436	C. 0.467	E. 0.466	G. 0.410
<u>.436</u>	<u>.468</u>	<u>.465</u>	<u>.410</u>
<u>.439</u>	<u>.465</u>	<u>.464</u>	<u>.412</u>
<u>.436</u>	<u>.463</u>	<u>.462</u>	<u>.410</u>
<u>.437</u>	<u>.462</u>	<u>.465</u>	<u>.410</u>
<u>.435</u>	<u>.468</u>	<u>.463</u>	<u>.415</u>
<u>.434</u>	<u>.463</u>	<u>.462</u>	<u>.414</u>
<u>.430</u>	<u>.465</u>	<u>.461</u>	<u>.413</u>
Av. 0.435	Av. 0.465	Av. 0.464	Av. 0.412

A diagram showing a rectangular plot of land. The top boundary is labeled 'KA' at the right end. The bottom boundary is labeled 'F. Alot of small pits' at the right end. The left boundary has two points labeled 'F)' and 'G)' from top to bottom. The top boundary has two points labeled 'E D' and 'S' from left to right. The bottom boundary has two points labeled 'F)' and 'G)' from left to right. The plot is divided into two sections by a vertical line. The left section is labeled 'F)' and 'G)' on the left boundary. The right section is labeled 'F. Alot of small pits' on the right boundary.

A.	0.481	B.	0.409	C.	0.487	D.	0.423
	.481		.408		.486		.421
	.481		.407		.479		.424
	.480		.409		.479		.424
	.479		.410		.482		.425
	.479		.411		.481		.420
	.477		.407		.480		.421
	.476		.406		.483		.421
Av.	0.479	Av.	0.408	Av.	0.482	Av.	0.422

A.	0.368	B.	0.387	C.	0.459	D.	0.429
	.365		.386		.459		.427
	.368		.384		.457		.425
	.368		.384		.458		.426
	.365		.383		.458		.429
	.365		.387		.460		.430
	.364		.388		.460		.428
	.360		.388		.455		.427
Av.	0.365	Av.	0.386	Av.	0.458	Av.	0.428

COMMENTS, CALIBRATIONS:

GENERAL PIER CONDITION:

WISWELL, INC.

U.S. NAVAL BASE GUANTANAMO BAY, CUBA, PIER LIMA


DATE: 8/2/79 BENT # 37 ☒ PLUMB ☐ BATTER PILE # F

CONDITION OF CAP: \_\_\_\_\_

CONDITION OF JACKET: \_\_\_\_\_

ULTRASONIC READING:

ELEV: Under Jacket




F. Very Deep  
Pits  
Base of Pits  
.200 - .250

A.	0.463	C.	0.480	E.	0.453	G.	0.402
	.463		.481		.455		.398
	.461		.482		.454		.397
	.464		.484		.453		.396
	.464		.483		.450		.394
	.465		.481		.451		.393
	.465		.480		.452		.390
	.465		.481		.450		.391
Av.	0.464	Av.	0.482	Av.	0.452	Av.	0.395

B.	0.433	D.	0.471	F.	0.451
	.433		.470		.449
	.432		.465		.445
	.435		.466		.441
	.434		.456		.442
	.431		.466		.441
	.430		.464		.440
	.429		.462		.441
Av.	0.432	Av.	0.465	Av.	0.444


ELEV: -17'



C. Large Pit  
.290 Center  
of Pit

A.	0.433	B.	0.441	C.	0.488	D.	0.489
	.433		.440		.488		.489
	.429		.439		.487		.488
	.428		.439		.486		.498
	.429		.437		.486		.488
	.427		.435		.485		.487
	.426		.432		.483		.488
	.428		.431		.480		.488
Av.	0.429	Av.	0.437	Av.	0.485	Av.	0.489

ELEV: -30'



S.W. Corner  
Bent Convex  
Deflection

A.	0.412	B.	0.388	C.	0.433	D.	0.433
	.412		.386		.429		.433
	.413		.387		.428		.434
	.415		.385		.429		.431
	.416		.386		.430		.433
	.411		.385		.430		.433
	.412		.386		.429		.435
	.413		.388		.428		.433
Av.	0.413	Av.	0.386	Av.	0.430	Av.	0.433

COMMENTS, CALIBRATIONS: \_\_\_\_\_

GENERAL PIER CONDITION: \_\_\_\_\_



WISWELL, INC.

U.S. NAVAL BASE GUANTANAMO BAY, CUBA, PIER LIMA


DATE: 8/1/79 BENT # 37 ☒ PLUMB ☐ BATTER PILE # G

CONDITION OF CAP: \_\_\_\_\_

CONDITION OF JACKET: \_\_\_\_\_

ULTRASONIC READING:

ELEV: Under Jacket




A - Alot of  
Small Pits

A.	0.375	C.	0.434	E.	0.417	G.	0.417
	.377		.436		.418		.416
	.378		.435		.419		.418
	.378		.473		.415		.415
	.377		.472		.410		.416
	.375		.476		.412		.415
	.376		.474		.414		.412
	.377		.475		.414		.413
Av.	0.377	Av.	0.459	Av.	0.415	Av.	0.415
B.	0.434	D.	0.455	F.	0.378		
	.435		.452		.379		
	.435		.451		.370		
	.436		.449		.381		
	.430		.448		.378		
	.432		.451		.379		
	.431		.452		.381		
	.429		.449		.379		
Av.	0.433	Av.	0.451	Av.	0.378		

ELEV: -20'


Test Block =



0.488  
B - Shallow  
Pit  
2"x2" hole  
1' above  
20' Depth  
Flange S.E.  
Corner

A.	0.457	B.	0.357	C.	0.371	D.	0.370
	.460		.359		.373		.370
	.459		.356		.375		.378
	.460		.355		.377		.379
	.459		.356		.378		.376
	.461		.356		.370		.373
	.462		.353		.375		.374
	.455		.354		.377		.373
Av.	0.459	Av.	0.356	Av.	0.375	Av.	0.374

ELEV: -35'



D - Shallow  
Pits  
C - Shallow  
Pits

A.	0.477	B.	0.473	C.	0.396	D.	0.382
	.478		.473		.396		.382
	.478		.472		.395		.380
	.471		.476		.393		.381
	.478		.479		.403		.385
	.477		.473		.401		.386
	.477		.481		.406		.385
	.478		.470		.398		.381
Av.	0.477	Av.	0.475	Av.	0.399	Av.	0.383

COMMENTS, CALIBRATIONS: \_\_\_\_\_

GENERAL PIER CONDITION: \_\_\_\_\_

WISWELL, INC.

U.S. NAVAL BASE GUANTANAMO BAY, CUBA, PIER LIMA


DATE: 8/1/79 BENT # 40 ☒ PLUMB ☐ BATTER FILE # A

CONDITION OF CAP: \_\_\_\_\_

CONDITION OF JACKET: \_\_\_\_\_


ULTRASONIC READING:

ELEV: Under Jacket



	A.	0.430	C.	0.443	E.	0.481	G.	0.467
		.431		.442		.482		.466
		.432		.441		.480		.465
		.431		.442		.481		.466
Area		.433		.442		.480		.465
where jacket		.434		.442		.482		.464
was removed		.435		.445		.480		.465
thickness in		.437		.444		.481		.467
Pits .30-.34		Av. 0.433		Av. 0.443		Av. 0.481		Av. 0.466
Around Pits	B.	0.389	D.	0.464	F.	0.378		
.42-.47		.387		.463		.376		
		.387		.462		.372		
		.388		.461		.376		
		.387		.463		.377		
		.389		.464		.375		
		.386		.464		.379		
		.384		.461		.375		
		Av. 0.387		Av. 0.463		Av. 0.376		


ELEV: -18'



C - Readings  
in a pit

	A.	0.473	B.	0.433	C.	0.375	D.	0.363
		.472		.432		.374		.362
		.473		.438		.372		.361
		.471		.437		.374		.367
		.471		.437		.372		.364
		.474		.436		.373		.365
		.475		.439		.372		.367
		.473		.431		.371		.362
		Av. 0.473		Av. 0.435		Av. 0.373		Av. 0.364

ELEV: -30'



	A.	0.449	B.	0.431	C.	0.458	D.	0.448
		.450		.432		.457		.447
		.451		.432		.459		.448
		.450		.435		.461		.446
		.448		.437		.457		.447
		.452		.431		.462		.450
		.454		.434		.460		.451
		.451		.432		.461		.449
		Av. 0.451		Av. 0.435		Av. 0.455		Av. 0.448

COMMENTS, CALIBRATIONS: \_\_\_\_\_

GENERAL PIER CONDITION: \_\_\_\_\_

WISWELL, INC.

U.S. NAVAL BASE GUANTANAMO BAY, CUBA, PIER LIMA


DATE: 8/1/79 BENT # 40 ☒ PLUMB ☐ BATTER PILE # B

CONDITION OF CAP: \_\_\_\_\_

CONDITION OF JACKET: \_\_\_\_\_

ULTRASONIC READING:


ELEV: Under Jacket



A lot of  
Small Pits  
  
2"x2" hole  
Edge of  
Flange


A.	0.422	C.	0.380	E.	0.420	G.	0.418
	.418		.380		.419		.418
	.420		.380		.427		.417
	.423		.381		.418		.419
	.422		.383		.419		.420
	.422		.383		.418		.421
	.423		.384		.418		.420
	.424		.382		.417		.421
Av.	0.422	Av.	0.382	Av.	0.420	Av.	0.419
B.	0.320	D.	0.402	F.	0.429		
	.321		.403		.423		
	.317		.404		.431		
	.322		.404		.431		
	.321		.405		.432		
	.322		.405		.433		
	.323		.403		.431		
	.322		.401		.431		
Av.	0.321	Av.	0.403	Av.	0.430		

ELEV: -18'



A.	0.457	B.	0.480	C.	0.450	D.	0.441
	.456		.481		.451		.441
	.457		.484		.449		.441
	.457		.483		.449		.444
	.457		.481		.451		.439
	.456		.479		.450		.440
	.478		.479		.451		.439
	.457		.477		.446		.438
Av.	0.459	Av.	0.480	Av.	0.450	Av.	0.440

ELEV: -29'



A.	0.362	B.	0.382	C.	0.442	D.	0.457
	.362		.382		.441		.454
	.361		.381		.442		.454
	.360		.380		.440		.455
	.361		.381		.442		.453
	.362		.381		.444		.452
	.359		.380		.443		.452
	.356		.382		.443		.451
Av.	0.361	Av.	0.381	Av.	0.442	Av.	0.454

COMMENTS, CALIBRATIONS: \_\_\_\_\_

GENERAL PIER CONDITION: \_\_\_\_\_

WISWELL, INC.

U.S. NAVAL BASE GUANTANAMO BAY, CUBA, PIER LIMA


DATE: 8/1/79 BENT # 40 ☒ PLUMB ☐ BATTER FILE # C

CONDITION OF CAP: \_\_\_\_\_

CONDITION OF JACKET: \_\_\_\_\_

ULTRASONIC READING:

ELEV: Under Jacket




B - Pit  
Behind  
Area

E - Hole  
Each side  
Flange

A.	0.399	C.	0.467	E.	0.473	G.	0.404
	.399		.467		.475		.403
	.395		.460		.474		.406
	.398		.460		.478		.405
	.398		.459		.475		.407
	.396		.459		.474		.405
	.397		.460		.476		.408
	.398		.462		.482		.408
	Av. 0.398		Av. 0.462		Av. 0.476		Av. 0.406
B.	0.166	D.	0.425	F.	0.411		
	.166		.425		.411		
	.167		.418		.411		
	.169		.418		.410		
	.170		.425		.411		
	.167		.402		.410		
	.169		.402		.410		
	.166		.422		.411		
	Av. 0.168		Av. 0.417		Av. 0.410		

ELEV: -19'




Slight Loss  
of Flange  
Area (D.W.)

A.	0.343	B.	0.161	C.	0.435	D.	0.406
	.341		.167		.437		.407
	.345		.169		.437		.408
	.347		.173		.446		.407
	.346		.166		.425		.407
	.347		.166		.429		.408
	.346		.176		.427		.410
	.345		.169		.428		.410
	Av. 0.345		Av. 0.168		Av. 0.433		Av. 0.408

ELEV: -28'

M.L.



D - Hole in  
web area  
1"x1"

A.	0.474	B.	0.422	C.	0.433	D.	0.373
	.474		.426		.433		.375
	.475		.427		.436		.376
	.473		.429		.433		.373
	.474		.422		.435		.377
	.479		.424		.434		.376
	.476		.429		.433		.375
	.474		.428		.434		.374
	Av. 0.475		Av. 0.425		Av. 0.434		Av. 0.375

COMMENTS, CALIBRATIONS: \_\_\_\_\_

GENERAL PIER CONDITION: \_\_\_\_\_

WISWELL, INC.

U.S. NAVAL BASE GUANTANAMO BAY, CUBA, PIER LIMA


DATE: 8/1/79 BENT # 40 ☒ PLUMB ☐ BATTER PILE # D

CONDITION OF CAP: \_\_\_\_\_

CONDITION OF JACKET: \_\_\_\_\_


ULTRASONIC READING:

	A.	0.419	C.	0.461	E.	0.370	G.	0.487
		.420		.460		.370		.487
ELEV: <u>Under Jacket</u>		.425		.459		.376		.488
E - slight		.409		.460		.369		.488
pitting		.410		.465		.370		.480
.25 deep		.418		.469		.367		.480
		.422		.465		.366		.481
		.424		.462		.366		.485
B - long		Av. 0.418		Av. 0.463		Av. 0.370		Av. 0.485
pit .30	B.	0.455	D.	0.441	F.	0.473		
deep		.452		.440		.473		
		.451		.434		.473		
		.454		.435		.472		
		.453		.436		.470		
		.451		.440		.471		
		.457		.441		.473		
				.437		.472		
		Av. 0.453		Av. 0.439		Av. 0.472		




ELEV: -19

	A.	0.426	B.	0.449	C.	0.388	D.	0.470
		.426		.448		.389		.470
		.425		.447		.394		.469
		.429		.449		.391		.468
		.421		.457		.388		.463
		.420		.456		.394		.457
		.419		.455		.393		.460
		.419		.454		.393		.465
		Av. 0.423		Av. 0.452		Av. 0.391		Av. 0.465



ELEV: -28 ML

	A.	0.449	B.	0.465	C.	0.386	D.	0.473
		.449		.463		.386		.472
		.471		.461		.388		.471
		.473		.463		.389		.477
		.469		.461		.394		.471
		.468		.464		.385		.471
		.470		.462		.387		.470
		.472		.465		.384		.471
		Av. 0.465		Av. 0.463		Av. 0.387		Av. 0.472



COMMENTS, CALIBRATIONS: \_\_\_\_\_

GENERAL PIER CONDITION: \_\_\_\_\_

WISWELL, INC.

U.S. NAVAL BASE GUANTANAMO BAY, CUBA, PIER LIMA


DATE: 8/1/79 BENT # 40 ☒ PLUMB ☐ BATTER FILE # E

CONDITION OF CAP: \_\_\_\_\_

CONDITION OF JACKET: \_\_\_\_\_

ULTRASONIC READING:


ELEV: Under Jacket A\*



F - All small pits hard to get good readings

A.	0.416	C.	0.473	E.	0.480	G.	0.408
	.414		.473		.481		.409
	.411		.476		.475		.402
	.416		.478		.471		.411
	.421		.480		.474		.402
	.415		.477		.475		.400
	.414		.475		.481		.399
	.414		.473		.483		.403
Av.	0.415	Av.	0.476	Av.	0.478	Av.	0.404
B.	0.488	D.	0.473	F.	0.386		
	.478		.474		.386		
	.489		.473		.385		
	.480		.475		.380		
	.482		.474		.380		
	.476		.475		.386		
	.480		.476		.384		
	.484		.478		.383		
Av.	0.482	Av.	0.478	Av.	0.384		


ELEV: -20'



B - Small pits

A.	0.424	B.	0.466	C.	0.425	D.	0.428
	.425		.465		.425		.426
	.428		.467		.427		.429
	.427		.472		.433		.430
	.424		.470		.433		.432
	.427		.466		.426		.426
	.428		.465		.421		.433
	.432		.468		.418		.431
Av.	0.427	Av.	0.467	Av.	0.426	Av.	0.429

ELEV: -30



A.	0.479	B.	0.358	C.	0.402	D.	0.375
	.478		.359		.402		.379
	.488		.356		.398		.380
	.488		.355		.399		.378
	.483		.356		.410		.375
	.488		.357		.412		.379
	.484		.355		.402		.401
	.486		.356				
Av.	0.484	Av.	0.357	Av.	0.404	Av.	0.381

COMMENTS, CALIBRATIONS: #1 .487, .488 / #2 .488 Test Block

GENERAL PIER CONDITION: A\* 6" indent in flange 1 1/2" deep plus large pit

WISWELL, INC.


U.S. NAVAL BASE GUANTANAMO BAY, CUBA, PIER LIMA

DATE: 8/1/79 BENT # 40 ☒ PLUMB ☐ BATTER PILE # F

CONDITION OF CAP: \_\_\_\_\_


CONDITION OF JACKET: \_\_\_\_\_

ULTRASONIC READING:	A.* 0.407	C.** 0.423	E. 0.353	G. 0.421
	.409	.425	.352	.423
ELEV: Under Jacket	.422	.424	.350	.433
	.411	.418	.351	.430
	.418	.418	.355	.425
C - Thickness	.410	.417	.360	.419
in pit .37	.411	.411	.351	.417
Beside pit		.414	.346	.424
.42	Av. 0.412	Av. 0.419	Av. 0.352	Av. 0.424
	B. 0.457	D. 0.410	F*** 0.428	
	.462	.411	.429	
	.463	.401	.430	
	.464	.402	.433	
	.457	.402	.425	
	.463	.400	.424	
	.457	.402	.426	
	.466	.411	.429	
	Av. 0.461	Av. 0.405	Av. 0.428	




\*Severe knife edge - knife edge  
into flange 2 1/2"  
\*\*Large pit  
\*\*\*Regular pitting

ELEV: -21	A. 0.425	B. 0.480	C. 0.448	D. 0.439
	.425	.480	.449	.438
	.430	.481	.450	.440
	.437	.477	.457	.441
	.432	.480	.462	.439
	.433	.473	.459	.448
	.430	.476	.467	.440
	.429	.480	.487	.447
	Av. 0.430	Av. 0.478	Av. 0.460	Av. 0.442



ELEV: -33	A. 0.473	B. 0.458	C. 0.488	D. 0.470
	.474	.453	.488	.471
	.470	.459	.489	.479
	.475	.457	.487	.485
	.465	.465	.468	.478
	.468	.465	.470	.473
	.465	.460	.470	.473
	.472	.463	.473	.476
	Av. 0.470	Av. 0.460	Av. 0.460	Av. 0.476



COMMENTS, CALIBRATIONS: \_\_\_\_\_

GENERAL PIER CONDITION: \_\_\_\_\_

WISWELL, INC.

U.S. NAVAL BASE GUANTANAMO BAY, CUBA, PIER LIMA


DATE: 8/1/79 BENT # 40 ☒ PLUMB ☐ BATTER PILE # G

CONDITION OF CAP: \_\_\_\_\_

CONDITION OF JACKET: \_\_\_\_\_


ULTRASONIC READING:

ELEV: Under Cap



A.	0.482	C.	0.453	E.	0.466	G.	0.496
	.473		.459		.465		.497
	.488		.460		.462		.499
	.498		.462		.459		.496
	.488		.463		.458		.477
	.496		.458		.458		.478
	.489		.458		.452		.474
					.458		.476
	Av. 0.488		Av. 0.459		Av. 0.460		Av. 0.488
B.	0.475	D.	0.418	F.	0.485		
	.477		.419		.487		
	.480		.422		.483		
	.478		.418		.484		
	.476		.417		.485		
	.486		.419		.486		
	.477		.420		.494		
			.417				
	Av. 0.479		Av. 0.419		Av. 0.486		


ELEV: -20



\*Flange deformation 3" inward  
bent is at reading "B"

A.*	0.431	B.	0.367	C.	0.346	D.	0.466
	.433		.361		.351		.465
	.426		.367		.354		.471
	.430		.356		.351		.473
	.429		.355		.349		.472
	.424		.367		.347		.481
	.433		.364		.347		.477
	.431		.346		.351		.469
	Av. 0.430		Av. 0.360		Av. 0.349		Av. 0.471

ELEV: -33



A.	0.473	B.	0.481	C.	0.449	D.	0.473
	.473		.485		.446		.473
	.481		.485		.451		.472
	.481		.486		.457		.475
	.482		.488		.449		.465
	.478		.482		.431		.477
	.480		.480		.445		.471
	.479		.481		.457		.472
	Av. 0.478		Av. 0.484		Av. 0.448		Av. 0.472

COMMENTS, CALIBRATIONS:

Topside 199-200 internal test block

GENERAL PIER CONDITION:



WISWELL, INC.

U.S. NAVAL BASE GUANTANAMO BAY, CUBA, PIER LIMA


DATE: 8/2/79 BENT # 79 ☒ PLUMB ☐ BATTER PILE # F

CONDITION OF CAP: \_\_\_\_\_

CONDITION OF JACKET: \_\_\_\_\_

ULTRASONIC READING:

ELEV: Under Jacket




D - Large  
Pit .330 deep  
2"x3"

G - Large  
Pit .296  
deep  
1" x 2 1/2"


A.	0.459	C.	0.450	E.	0.481	G.	0.355
	.460		.450		.487		.355
	.462		.452		.484		.354
	.468		.451		.488		.356
	.469		.449		.486		.352
	.466		.450		.489		.351
	.464		.453		.488		.352
	.460		.452		.488		.350
Av.	0.464	Av.	0.451	Av.	0.486	Av.	0.353
B.	0.427	D.	0.457	F.	0.481		
	.429		.458		.481		
	.421		.462		.482		
	.422		.458		.480		
	.428		.452		.479		
	.429		.452		.476		
	.430		.451		.475		
	.430		.450		.474		
Av.	0.427	Av.	0.455	Av.	0.479		

ELEV: -15'



A.	0.457	B.	0.324	C.	0.440	D.	0.447
	.458		.325		.437		.440
	.459		.323		.439		.439
	.458		.322		.436		.437
	.462		.321		.433		.436
	.458		.320		.431		.443
	.458		.322		.430		.442
	.454		.321		.431		.441
Av.	0.458	Av.	0.322	Av.	0.435	Av.	0.441

ELEV: -31'



B - Pit  
C - Pit  
D - Large Pit

A.	0.488	B.	0.339	C.	0.316	D.	0.452
	.488		.332		.307		.449
	.489		.330		.303		.448
	.489		.331		.310		.446
	.490		.332		.309		.437
	.491		.334		.307		.434
	.491		.331		.308		.434
	.491		.332		.301		.432
Av.	0.490	Av.	0.335	Av.	0.308	Av.	0.442

COMMENTS, CALIBRATIONS: \_\_\_\_\_

GENERAL PIER CONDITION: \_\_\_\_\_

U.S. NAVAL BASE GUANTANAMO BAY, CUBA, PIER LIMA

CONDITION OF CAP: \_\_\_\_\_

CONDITION OF JACKET: \_\_\_\_\_

A. 0.457	C. 0.394	E. 0.449	G. 0.441
.454	.394	.449	.440
.453	.395	.448	.444
.453	.394	.447	.441
.453	.395	.442	.413
.458	.397	.440	.413
.457	.396	.448	.412
.456	.397	.442	.411
Av. 0.455	Av. 0.395	Av. 0.446	Av. 0.427

B.	D.	F.
0.481	0.410	0.369
.483	.410	.369
.481	.411	.366
.480	.410	.369
.479	.419	.368
.484	.420	.362
.483	.408	.370
.487	.406	.369
Av. 0.482	Av. 0.412	Av. 0.368

A.	0.460	B.	0.388	C.	0.452	D.	0.391
	.463		.389		.449		.392
	.465		.389		.449		.394
	.460		.387		.455		.390
	.460		.386		.450		.392
	.459		.378		.457		.394
	.457		.377		.449		.394
	.457		.377		.447		.391
Av.	0.460	Av.	0.384	Av.	0.451	Av.	0.392

	P	C

C - Large Pit  
.184 inside  
3"x4"

A.	0.394	B.	0.447	C.	0.463	D.	0.446
	.396		.449		.464		.449
	.393		.450		.465		.447
	.397		.453		.467		.442
	.399		.452		.464		.447
	.392		.452		.463		.442
	.391		.453		.465		.440
	.390		.454		.466		.441
AV.	0.394	AV.	0.451	AV.	0.451	AV.	0.444

**COMMENTS, CALIBRATIONS:**

**GENERAL PIER CONDITION:**

**APPENDIX V**

**PIER LIMA  
NAVAL STATION, GUANTANAMO BAY, CUBA**

**GOVERNMENT FURNISHED INFORMATION**

GOVERNMENT FURNISHED INFORMATION

Yards & Docks Drawing #336505	Ship Repair Project, General Plan (1943)
Yards & Docks Drawing #470806	Rehabilitation of Repair Pier Lima, General Plan (1950)
Yards & Docks Drawing #470807	Rehabilitation of Repair Pier Lima, Typical Details-Outboard End
Yards & Docks Drawing #470808	Rehabilitation of Repair Pier Lima, Typical Details-Inboard End
NAVFAC Drawing #4001966	Repair Pier Lima--Maps, Plan & Section
NAVFAC Drawing #4001967	Repair Pier Lima--Part Plan
NAVFAC Drawing #4001968	Repair Pier Lima--Part Plan & Notes
NAVFAC Drawing #4001969	Repair Pier Lima--Part Plan & Details
NAVFAC Drawing #4001970	Repair Pier Lima--Fender System & Pile Details
NAVFAC Drawing #4001971	Repair Pier Lima--Details & Sections
NAVFAC Drawing #4001972	Repair Pier Lima--Details & Sections
NAVFAC Drawing #4001973	Repair Pier Lima--Plan Legend & Details Electrical
NAVFAC Drawing #4001974	Repair Pier Lima--Part Plan-Pier Electrical

"Point Paper on the Preliminary Underwater Survey of Pier Lima, Guantanamo Bay, Cuba" by Jack E. Baber (July 1979)

APPENDIX VI

PIER LIMA  
NAVAL STATION, GUANTANAMO BAY, CUBA

PETROGRAPHIC EXAMINATION FINDINGS  
as conducted by  
Construction Technology Laboratories

# construction technology laboratories

A DIVISION OF THE PORTLAND CEMENT ASSOCIATION

5420 Old Orchard Road Skokie, Illinois 60077 • Area Code 312 966-6200

September 6, 1979

Mr. George C. Wiswell, Jr.  
President  
Wiswell, Inc.  
3280 Post Road  
Southport, Connecticut 06490


Mr. Wiswell:

Attached is a report by D. H. Campbell giving results of petrographic examination of a large concrete sample transmitted by your letter of August 8.

We believe the report is complete and self-explanatory; however, if you have any questions or if we can be of further assistance, do not hesitate to contact us.

In keeping with our policy, we will retain your sample for a period of one year, at which time it will be discarded unless we receive word from you to the contrary.

Sincerely yours,

  
J. J. Spideler, Director  
Administrative and Technical Services

JJS/lg  
CT-0616

Copy to -  
W. E. Kunze  
E. Hognestad  
D. C. Sikes  
D. H. Campbell

Attachment

## Petrographic Services Report

Project No.: CT-0616

Date: September 4, 1979

Re: Deteriorated H-piling  
(Wiswell, Inc.)

A large concrete sample, weighing approximately 50 pounds reportedly taken from an H-piling (BP14-73) in the tidal zone of a U.S. Navy installation, has been received from Wiswell, Inc., Southport, Connecticut, for petrographic examination relating to extensive deterioration.

### Conclusions

The concrete is of extremely low quality, having a weak paste-aggregate bond. Evidence of extensive paste alteration is present.

### Methods

Procedures for petrographic (microscopic) examination are detailed in ASTM C-856, "Petrographic Examination of Hardened Concrete."

### Description and Discussion

An attempt to saw a slice from the concrete sample was only moderately successful. The paste is extremely soft and was severely eroded during the sawing operation and, consequently, could not be lapped.

Nevertheless, the sawed slice did reveal segregation of coarse aggregates (Photo 1), a natural gravel composed mainly of meta-quartzite, limestone, chert, and a few other sedimentary rock types. Aggregate top size is approximately 1/2 to 3/4 inch. The metaquartzite may be potentially alkali-reactive, but clear evidence of the reaction was not observed.

Fine aggregate is a natural sand composed of ordinary quartz, metaquartzite, chert, feldspar, and other minerals and rock fragments. Coarse to fine aggregate ratio is about 55/45. Paste-aggregate bond is extremely weak.

The soft cream-colored paste contains very few unhydrated portland cement clinker particles. Calcium hydroxide is scarce. Ettringite, a hydrated calcium sulfo-aluminate, is common as needle-like crystals on crack surfaces and within the paste. Carbonation of the paste on freshly cut surfaces is rapid in the laboratory atmosphere. The paste has a dull luster. These

data suggest a high water-cement ratio, although this interpretation is questionable because of the apparent deterioration of the paste. Other secondary alteration products detected by X-ray diffraction are brucite and chloro-aluminate hydrate, which are common products of sea-water attack. The concrete is not air-entrained. Wire mesh is severely corroded.

*D. H. Campbell (lg)*

D. H. Campbell, Supervisor  
Petrographic Services  
Technical Services Section

DHC/md  
CT-0616

Copy to-  
J. J. Shideler





Photo 1 -- Sawed slice showing extreme paste erosion and demonstrating the low strength of the material.

CT-0616

A-46

**APPENDIX VII**

**PIER LIMA  
NAVAL STATION, GUANTANAMO BAY, CUBA**

**PHOTOGRAPHS**



1. Two of the three man Wiswell, Inc. engineer/diver inspection team with dive station in background.



2. Getting to work.

A-47



3. View looking  
in a southerly  
direction straight  
out on Pier Lima.



4. View of G Row  
of Pier Lima taken  
from west side  
access ramp with  
dive station at  
Bent #30.



5. Even closer  
view of G Row  
showing Bents  
#20 to #26.



6. View of A Row looking shoreward from near outboard end.




7. Typical pile cap damage near outer end of pier, A Row.



8. Bent #37, Pile F - note 6" x 16" piece pulled away from main 12" x 16" timber pile cap. Note improper bearing of pile cap to pile. Inspection revealed that there were 3 bolt holes over Pile F and only 1 bolt in place and 4 bolt holes over Pile G and only 1 bolt in place.




9. Separated joint on west access ramp. Picture taken in a westerly direction.



10. Section between Bents #15 and #16 showing typical failed old deck. Note spalled concrete and deteriorated reinforcing.




11. Angular view over the edge, showing cracks radiating outwards from each of the flanges.



12. Bent #77, Pile F--no concrete over both right-hand flanges.



13. Bent #81, Pile F--no contact with cap.



14. Bent #81, Pile G--angular contact with cap. Not full bearing. Also typical loose bolt.





15. Batter pile between Bents #71 and #72, G Row, indicating minimal cover on one side.



16. Batter pile between Bents #67 and #68, G Row, showing minimal cover of concrete jacket, plus inadequate structural transfer of load across splice. Note unusual combination of bolt types used.



17. Bent #44, (not 45) Pile G--approximately 10 percent bearing between top of pile and pile cap. Note concrete on top of pile plate, doubtless from the time deck was resurfaced.



18. Batter between Bents #37 & #38 with a section of the flange removed to allow the pipe to pass. Also non-alignment of upper and lower batter. Improper splice design and improper bolting.


AD-A167 632

REPORT AND RECOMMENDATIONS ON UNDERWATER DAMAGE  
ASSESSMENT PTER LIMA NAUA. (U) HIRE CORP MCLEAN VA  
JASON PROGRAM OFFICE SEP 79 CHES/NAUFAC-FPO-7914  
UNCLASSIFIED NG2477-79-C-0837 F/G 13/2

2/2

ML2

END  
DATE  
FILMED  
6-86






19. Bent #57,  
Pile F--decreasing  
width as a result  
of delamination  
and corrosive  
action.



20. Bent #55,  
Pile F--typical  
corner split  
referred to in  
text. Generally  
speaking as a  
result of improper  
concrete coverage  
and resulting  
oxidation.



21. Bent #47,  
Pile F--top of  
typical old  
jacket showing  
corroded,  
reinforcing,  
deterioration &  
lack of  
concentricity.




22. Example of improperly filled form coupled with lack of concentricity.



23. Fender pile destroyed by limnoria at waterline.




24. Example of spalling adjacent to flange edge.



25. Close up view of 90 pound concrete sample removed from lower underwater portion of jacket on Bent #40, Row A. Note oxidation streaks as well as apparent voids in concrete. Note two deteriorated reinforcing rods coming from top.



26. Close up under jacket showing decreasing width of two flanges.



27. Pile on Bent #16, Row F, immediately under the cap showing some of the tools used in measuring. Also the picture clearly shows flange width being 0.310".



28. Cleaned & uncleaned area on pile on Bent #15, Row G, indicating the typical amount of bio-fouling at elevation immediately under cap and occasionally at mid-depth. Growth is of harder consistency at mudline than is pictured in this photograph.





29. View looking upwards, Bent #40, Row A, showing remains of old concrete jacket. This is section where concrete sample shown in photograph #25 was removed. Note knife edging of flange, decreasing width, and corrosion streak through concrete in line with edge of flange.




30. View looking upwards on Bent #40, Row A, on same general side, but on opposite flange. Note generally poor condition of concrete and decreasing width of flange.



31. Pile on Bent #40, Row B. Hole is immediately under cap. Note decreasing width on each of the three visible flanges.



32. Mudline photograph showing cleaned and uncleaned sections. Note the difference in types of marine growth. Also note absence of pits.



33. Cleaned section of web. Note the large pit upper right, as well as small pits upper left.

REFERENCE

Hosford, H.W. "Cathodic Protection of Marine Structures",  
Harco Paper HC-16, Harco Corp., Medina, Ohio

Rogers, Howard T., "Marine Corrosion Handbook", McGraw-  
Hill, New York

#### BIBLIOGRAPHY

Hosford, H.W. "Cathodic Protection of Marine Structures", Harco Paper HC-16, Harco Corp., Medina, Ohio

Rogers, Howard T., "Marine Corrosion Handbook", McGraw-Hill, New York

"Steel Construction Manual", American Institute of Steel Construction

"Steel H-piles", Bethlehem Steel Corporation, Bethlehem, Pennsylvania

END

DATE  
FILMED

6-86